

ASS. REC. BY:

REF: CS/EGT20004604/Mgd3

n2

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person): Pauline Soh of FGI Date/Time: 27/3/2020 @ 10:57am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 58462 Insured: YP 7394U

at Workshop m/s Automobile Integrated Tel: 9119 8371

of 23 Kaki Bukit Ave 4 # 04-01

Policy No: Claim No: CDMFG20000517

Sum Insured: Excess:

Make of Veh: D.O.A. 24/03/2020
(Client's Record)CA / REV / REP. / REV 24 HRS (up) 30/3/2020 @ after 12:30pm
H.O.D. Endorsement:

Date/Time: 11:32am @ 27/3/2020 Person Contacted: Jacye Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	✓
	GBD 58462 - NA / M64 / 9001586 / h4	DOA: 27/01/2019	
31/3/2020 @ 3pm	Informed ERGO, we are pending estimate from repairer		
	YP 7394U - X		
01/4/2020	10:04am visited to ERGO via Merimen.		

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3D58462
at Workshop m/s A/m 1230

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 341.

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: G3D 58462 Yr Regn: 2/1/15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace c.c 2982

Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: 157388 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P900L53925

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/3/20 D.O.I. 30/3/20

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 29007 Bol 4yrs 9m.

1/4/20 4/5 #3200 conf. with Kelvin (Ued 89108.51, 747.)

RECEIVED 1 APR 2020

Date/Time, File Pass to?

☐: Preli. Report

1) 01/4/2013

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

350

11

361

Report Format :

Lump Sum / I.B.I: (\$)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Apr 2020

Preliminary Advice

Insured Vehicle No	: YP2394U		
TP Vehicle No	: GBD5846Z	Accident Date	: 24/03/2020
Make	: TOYOTA HIACE	Assignment Date	: 27/03/2020
Date of Inspection	: 30/03/2020	Est. Duration of Repair	: 4.00
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,308.51
Revised Amount	:S\$	4,058.89
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,058.89
 Lump Sum Repair	 :S\$	 3,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

admin

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Friday, 27 March 2020 10:57 AM
To: Admin-D (LKKAUTO (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAUTO (Meikwan@lkkauto.com))
Cc: Zheng Hanyang; Phoebe Xie; automim.claim@gmail.com
Subject: FW: Claims ref no. (P) CDMFG20000517 NOA- GBD5846Z // TP Claim 24.03.2020

Date Classification : Confidential, C3

**** NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

Thank you.

Warmest Regards,
Pauline Soh
Executive

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard #04-05 | Suntec Tower Five | Singapore 038985
DID.: +65 6829 9194

pauline.soh@ergo.com.sg | www.ergo.com.sg

ERGO

A Munich Re company

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Thursday, 26 March 2020 9:31 am
To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Cc: Jacelyn Foo <jacelyn.foo@ergo.com.sg>; Zheng Hanyang <hanyang.zheng@ergo.com.sg>; Phoebe Xie

<phoebe.xie@ergo.com.sg>

Subject: Re: Claims ref no. (P) CDMFG20000517 NOA- GBD5846Z // TP Claim 24.03.2020

Hi Pauline,

We would like to appoint surveyor from LKK to conduct survey.

Thank you.

Regards,
Jacyne

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

On Thu, Mar 26, 2020 at 9:30 AM ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg> wrote:

Date Classification : Confidential, C3

Dear Jacyne,

We would like to conduct a PRI survey, please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd

9	AJAX	AJAX Inspection Services Pte Ltd
10	AA	Appraisal Associate

Warmest Regards,

Pauline Soh

Executive

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard #04-05 | Suntec Tower Five | Singapore 038985

DID.: +65 6829 9194

pauline.soh@ergo.com.sg | www.ergo.com.sg

ERGO

A Munich Re company

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: AIM PTE LTD <automim.claim@gmail.com>

Sent: Wednesday, 25 March 2020 3:21 pm

To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Subject: NOA- GBD5846Z // TP Claim 24.03.2020

Hi,

Please find attached to advise further.

Thank you.

Regards,

Jacyne

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 31 March 2020 3:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE GBD 5846Z (YOUR REF: CDMFG20000517)

This mail is associated with :

***GBD5846Z**
[YP2394U]
TP

Mar 24 2020 12:00AM

Automobile Integrated Management Pte Ltd

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBD 5846Z on 30/03/2020.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

SGCARMART

CONNECT

Business Success & Growth

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2017 Volkswagen Scirocco GP 1.4 Lady Owner...



Original Condition, Low Mileage,
Parked Indoors, Well
Maintained.

Direct Owner - StarAd

Lake View Credit Pte Ltd








View our cars

> Low prices guaranteed

> Specialist in Japanese cars

> Easy loan approval

> All terms are negotiable

Browse by Category		Sort by Date Posted		20 results/page			
16 vehicles		Hiace		Advanced Search		Submit	
Make		Model		Price		Depreciation	
Search Selection		Hiace		Any		Any	
				2015		Any	
				Any		Any	
				Any		Available	
		Toyota Hiace Commuter 3.0A GL		\$43,800		\$8,770 /yr	
		Fuel Type: Diesel		28-Mar-2015		2,982 cc	
		Think One Automobile & Trading		348,945 km		Bus	
		Posted: 29-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
		Toyota Hiace 3.0A DX		\$36,800		\$7,240 /yr	
		Fuel Type: Diesel		29-Apr-2015		2,982 cc	
		Automatic Unit! Very Low Mileage For It's Age! Thi S Is The Most Reliable And Versatile Toyota Van In The Market With Lowest Mainten...		150,000 km		Van	
		Posted: 28-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
		Toyota Hiace Commuter 3.0A		\$45,800		\$8,100 /yr	
		Fuel Type: Diesel		25-Nov-2015		2,982 cc	
		Please Call To Arrange For Viewing Thank You.				Bus	
		Posted: 28-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
		Toyota Hiace 3.0M		\$36,800		\$7,400 /yr	
		Fuel Type: Diesel		20-Mar-2015		2,982 cc	
		Nice Paintwork, Nice Cushion, Beautiful And Clean Interior, Well Maintained, Serviced Regularly, Flexible Loan Available At Low Interest...				Van	
		Posted: 27-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
		Toyota Hiace (For Lease)					
		\$1,250/mth Toyota Hiace is tailored to suit your business requirements @ only \$1150/mth !!					
		More info about this vehicle					
		Toyota Hiace Commuter 3.0A High Roof		\$47,800		\$8,420 /yr	
		Fuel Type: Diesel		02-Dec-2015		2,982 cc	
		6 Months Warranty, Excellent Condition, Bank Loan/In House Loan Available, Trade In Welcome,				Bus	
		Posted: 27-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
		Toyota Hiace 3.0A DX		\$41,800		\$7,470 /yr	
		Fuel Type: Diesel		02-Nov-2015		2,982 cc	
		11/2015 Toyota Hiace 3.0 DX Auto 5 Doors Rear Aircon, One Owner, COE \$36,312 New Paint And New Facelift.				Van	
		Think One Automobile & Trading					
		Posted: 27-Mar-2020		Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace			
Compare		Toyota Hiace 3.0A DX		\$42,800		\$8,080 /yr	
				16-Jul-2015		2,982 cc	
						Van	
						Available	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 226D

Vehicle Details

Vehicle No.: GBD5846Z

Vehicle to be Exported: No

Intended Deregistration Date: 30 Mar 2020

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR
MANUAL

Primary Colour: White

Manufacturing Year: 2014

Engine No.: 1KD2461512

Chassis No.: JTFHT02P900153925

Maximum Power Output: -

Open Market Value: \$27,502.00

Original Registration Date: 02 Jan 2015

First Registration Date: 02 Jan 2015

Transfer Count: 1

Actual ARF Paid: \$1,376.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 01 Jan 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$61,000.00

COE Rebate Amount: \$29,007.00

Total Rebate Amount: \$29,007.00

The information contained herein is correct as at 30 Mar 2020

OK

MCHM20036124 / Cheng Hoe Motor Pte Ltd - Yishun
 ENTRY DATE & TIME: 24/03/2020 14:35
 SUBMITTED BY: SHARON CHIONG BENG CHOON

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/03/2020 14:35
 Date Of Accident 24/03/2020 05:35
 Exact Location Of Accident 11 SENOKO WAY CAR PARK
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP2394U
Insured/Policyholder
 Name Of Registered Owner ZERO SPOT LAUNDRY SERVICE PTE LTD
 Co Reg No 199707580W
 Email Address SEPEIYONG@ZEROSPOT.COM
 Mobile Phone No
 Alternative Phone No Office-68521171

Vehicle Particulars

Manufacturer MITSUBISHI
 Model CANTER FECX1HR4SDED
 Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company ERGO INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number DMFG20000606
 Cover Note Number 01/01/20 - 31/12/20

Driver

Name of Driver TAN SONG PENG
 NRIC No S1316757E
 Date Of Birth 01/12/1958
 Occupation OUTDOOR
 Date Of Driving Pass 09/01/1999

Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98387044
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 109 SERANGOON NORTH AVE 1 #04-645
Postcode	550109
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	DARK
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD5846Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	CO.: DHL
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: YP2394U
 INSURER : ECG
 DATE & TIME: 24/3/20 @ 05:25am


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 24/3/20
 Reporting Centre Personnel's Signature
 Name: CYS
 NRIC/FIN No.:

ESTIMATE

Our Ref: AC2020026/TP/GBD5846Z-24.03.2020

Vehicle number: GBD5846Z

Vehicle Make & Model: TOYOTA HIACE

*not authorized
make
2/s @ 3200
30/3/20
for repair after repair*

Items	Qty	List Items
1	1	Front bonnet
2	1	Front bonnet lock
3	2	Front bonnet hinges - L/R @ 65.50
4	1	Front bumper <i>496.30</i>
5	2	Front bumper brackets - L/R @ 201.10
6	1	Front bumper beam
7	1	Front bumper reinforcement
8	2	Front bumper side retainers - L/R @ 124.10
9	1	Front grille - Top <i>281.50</i>
10	1	Front grille - Lower <i>330.80</i>
11	1	Front grille base
12	2	Front headlamps - L/R @ 704.35
13	1	Front corner panel - LH
14	1	Front door - LH
15	1	Front brace panel
16	1	Front support panel
17	1	Front support panel seal
18	1	Air con condenser
19	1	Radiator assy
20	1	Radiator sub tank
21	1	Wiper tank
22	1	Wiper panel garnish

	Amount \$
<i>body</i>	727.10 ✓
<i>tw</i>	131.50 ✓
<i>11</i>	131.00 X
<i>22</i>	595.70 ✓
<i>11</i>	402.20 X
<i>11</i>	232.60 X
<i>11</i>	497.10 X
<i>11</i>	248.20 X
<i>one</i>	435.10 ✓
<i>one</i>	405.95 ✓
<i>25</i>	410.35 X
<i>nl scene</i>	1,408.70 <i>IPC</i>
<i>11</i>	370.20 X
<i>11</i>	1,658.60 X
<i>11</i>	110.25 X
<i>sent</i>	399.10 ✓
<i>11</i>	81.60 X
<i>11</i>	1,024.10 X
<i>11</i>	1,887.60 X
<i>11</i>	391.60 X
<i>De</i>	241.20 ✓
<i>11</i>	441.60 X

Sub-total	12,231.35
Less 25%	3,057.84
Total List	9,173.51

Special Nett Items

23	1	Front no. plate
24	1 set	Front bumper clip
25	1 set	Advertisement sticker

<i>nl sent</i>	40.00 X
<i>ner</i>	45.00 ✓
<i>nl</i>	300.00 <i>280</i>


Total Special Nett 385.00

Labour charges

26	To check front electrical wiring	50.00	20
27	To remove, refix A/C condenser & refill A/C gas	180.00	100
28	To respray undercoating	120.00	30
29	To respray painting and etc	1,200.00	500
30	Panel beating, cut, weld remove & replacing above parts	1,200.00	600
Total Labour		2,750.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

12,308.51



P-3311.85
2576
P-2483.88
S.N-325.00
L-1250.00
4058.88
3247.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20004604/UQD3N2

Date: 01/04/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBD5846Z

Insured Vehicle No : YP2394U

Date of Loss: 24/03/2020

Nature of Claim:

TP

Claim No: CDMFG20000517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD5846Z

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2461512

Reg. Date: 02/01/2015 (Man. Year: 2014)

Chassis No: JTFHT02P900153925

Colour: Yellow

Odometer: 157388 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,558.51	2,808.89	6,749.62	70.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,250.00	1,500.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,308.51	4,058.89	8,249.62	67.02
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	12,308.51	3,200.00	9,108.51	74.00
+ GST 7.00/7.00% (S\$)	861.60	224.00	637.60	74.00
Nett Amount (S\$)	13,170.11	3,424.00	9,746.11	74.00

INSPECTION

Date of Assignment: 27/03/2020

Date Inspected: 30/03/2020 Inspected At:

Automobile Integrated Management Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2020)		
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBD5846Z)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Badly Dented	727.10 FL	*727.10 FL
2	1		*FRONT BONNET LOCK	Twisted	131.50 FL	*131.50 FL
3	2		*FRONT BONNET HINGES-L/R	Not Necessary	131.00 FL	*- FL
4	1		*FRONT BUMPER	Dented	595.70 FL	*496.30 FL
5	2		*FRONT BUMPER BRACKETS-L/R	Not Necessary	402.20 FL	*- FL
6	1		*FRONT BUMPER BEAM	Not Necessary	232.60 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINERS-L/R	Not Necessary	248.20 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	497.10 FL	*- FL
9	1		*FRONT GRILLE-TOP	Cracked	435.10 FL	*281.50 FL
10	1		*FRONT GRILLE-LOWER	Cracked	405.95 FL	*330.80 FL
11	1		*FRONT GRILLE BASE	No such part	410.35 FL	*- FL
12	1		*FRONT HEADLAMPS-L/R	N/s Cracked	1,408.70 FL	*704.35 FL
13	1		*FRONT CORNER PANEL-LH	Not Necessary	370.20 FL	*- FL
14	1		*FRONT DOOR-LH	Not Necessary	1,658.60 FL	*- FL
15	1		*FRONT BRACE PANEL	Not Necessary	110.25 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Bent	399.10 FL	*399.10 FL
17	1		*FRONT SUPPORT PANEL SEAL	Not Necessary	81.60 FL	*- FL
18	1		*AIR CON CONDENSER	Not Necessary	1,024.10 FL	*- FL
19	1		*RADIATOR ASSY	Not Necessary	1,887.60 FL	*- FL
20	1		*RADIATOR SUB TANK	Not Necessary	391.60 FL	*- FL
21	1		*WIPER TANK	Deformed	241.20 FL	*241.20 FL
22	1		*WIPER PANEL GARNISH	Not Necessary	441.60 FL	*- FL
23	1		*FRONT NO PLATE (BENT)	Not Consistent With The Impact	40.00 FS	*- FS
24	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
25	1		*SET ADVERTISEMENT STICKER	Necessary	300.00 FS	*280.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	12,616.35	3,636.85
- List Item Discount on L Items 25.00/25.00% (S\$)	3,057.84	827.96
Total Parts (S\$)	9,558.51	2,808.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	100.00
3	TO RESPRAY UNDERCOATING	New	120.00	30.00
4	TO RESPRAY PAINTING AND ETC	New	1,200.00	500.00
5	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,750.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >