



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

TIP CLAIM

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Lim Boon Kwang James 133 Lorong Ah Soo #04-420 Singapore 530133
	Document No	0
	Document Date	25/03/2020
		Mobile: 96981957

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	31/10/2016	SLH3290A	0	54492 84/TP/SLH3290A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W50J005764	2ZR1849325	60	Joe Tan Joo Seng	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P CLAIM ACC DATE:24/03/20 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB2 TO CHECK WIRING, LIGHTING AND CARRY OUT WATER LEAK TEST.				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, 790 - 1.5 REPAIR AND REPAIR R/F PORTION OF CAR				1980 2160.00
5	B	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED R/F 590 x 2 PORTION OF CAR.				1180 1770.00
6	1	T52030-68010 R/F BUMPER HOLE COVER, / MIS	1.00	85.50		85.50
7	2	T52611-68030 FRT BUMPER ABSORBER, X	1.00	101.90		101.90
8	3	T52115-68031 R/FRT BUMPER SUPPORT, / RR	1.00	62.80		62.80
9	4	T52119-68909 FRONT BUMPER COVER, / RR	1.00	591.80		591.80
10	5	T53119-68010 FRT GRILLE PROTECTOR, ?	1.00	29.40		29.40
11	6	T53112-68030 F/LOW RADIATOR GRILLE, / CUT (RH)	1.00	57.00		57.00
12	7	S52161-OK040 PIECE, RR BUMPER - MC	10.00	4.10		41.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4236771

TO SECURITY GUARD

4236771

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/03/2020  
TIME 15:53

VEHICLE NO SLH3290A

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor

Inchcape



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Lim Boon Kwang James 133 Lorong Ah Soo #04-420 Singapore 530133  Mobile: 96981957
	Document No	
	Document Date	
	0	
	25/03/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE2OR	31/10/2016	SLH3290A	0	54492 84/TP/SLH3290A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W50J005764	2ZR1849325	60	Joe Tan Joo Seng	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	8	T81510-47010 LAMP ASSY, FR TURN RH / MJ	1.00	102.10		102.10
14	9	T53101-68010 GRILLE SUB-ASSY, X	1.00	415.10		415.10
15	0	T81145-68100 UNIT, HEADLAMP / CM	1.00	1265.70		1265.70
16	1	T53811-68060 FENDER SUB-ASSY, RH X R	1.00	988.40		988.40
17	2	T53875-68020 R/FRT FENDER LINER, X	1.00	172.70		172.70
18	3	T90467-07201 CLIPS X	6.00	3.50		21.00

Steve (LKK) ml ml  
27/3/20, 3.15pm  
P/P  
By BL sy  
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,934.40	8,266.80
		Labour 4,332.40	GST 7.00% 578.60
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 8,845.48

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/03/2020  
TIME 15:53

VEHICLE NO SLH3290A

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors