

# TOYOTA

No : 196700086Z  
No : MR-8500000-9

## TIP CLAIM

### ESTIMATE

Get "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

[www.toyota.com.sg](http://www.toyota.com.sg)

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail

Account No

Customer Detail

THIRD PARTY CLAIM

S1000020 / TPCLAIM

Document No

0

Document Date

25/03/2020

Mr Lim Boon Kwang James

133 Lorong Ah Soo

#04-420

Singapore 530133

Mobile: 96981957

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	31/10/2016	SLH3290A	0	54492 84/TP/SLH3290A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W50J005764	22R1849325	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P CLAIM ACC DATE:24/03/20 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 TO CHECK WIRING, LIGHTING AND CARRY OUT WATER LEAK TEST.				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, 770 - 1.5				1980 2160.00
5	B	BP-RES2 TO REPAIR AND REPAIR R/F PORTION OF CAR				1180 1770.00
6	1	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED R/F 590 x 2				
6	1	T52030-68010 R/F BUMPER HOLE COVER, / MIS	1.00	85.50		85.50
7	2	T52611-68030 FRT BUMPER ABSORBER, X NN	1.00	101.90		101.90
8	3	T52115-68031 R/FRT BUMPER SUPPORT, / BR	1.00	62.80		62.80
9	4	T52119-68909 FRONT BUMPER COVER, - BR	1.00	591.80		591.80
10	5	T53119-68010 FRT GRILLE PROTECTOR, X NN	1.00	29.40		29.40
11	6	T53112-68030 F/LOW RADIATOR GRILLE, - CUT (RM)	1.00	57.00		57.00
12	7	S52161-OK040 PIECE, RR BUMPER - MC	10.00	4.10		41.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4236771

TO SECURITY GUARD

4236771

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/03/2020  
TIME 15:53

VEHICLE NO SLH3290A

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



## Borneo Motors

Inchcape



# TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

[www.toyota.com.sg](http://www.toyota.com.sg)

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no. : 6631 1188

No : 196700086Z  
No : MR-8500000-9

## ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Lim Boon Kwang James 133 Lorong Ah Soo #04-420 Singapore 530133  Mobile: 96981957
		Document No	
		0	
		Document Date	
		25/03/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	31/10/2016	SLH3290A	0	54492	84/TP/SLH3290A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W50J005764	22R1849325	60	Joe Tan Joo Seng	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	8	T81510-47010 LAMP ASSY, FR TURN RH / MJ	1.00	102.10		68.30 ✓ 102.10
14	9	T53101-68010 GRILLE SUB-ASSY, X NN	1.00	415.10		415.10
15	0	T81145-68100 UNIT, HEADLAMP / CPT	1.00	1265.70		1265.70
16	1	T53811-68060 FENDER SUB-ASSY, RH X R	1.00	988.40		988.40
17	2	T53875-68020 R/FRT FENDER LINER, X NN	1.00	172.70		172.70
18	3	T90467-07201 CLIPS X NN	6.00	3.50		21.00

Steve (LKK) ml pm  
27/3/20, 3.15pm  
P/P = \$4,784.50  
P/P  
By BL sy  
4 dys

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	8,266.80
	Please acknowledge receipt of vehicle	Parts	3,934.40	GST 7.00%
		Labour	4,332.40	
		Materials	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	8,845.48

PLEASE TEAR ALONG PERFORATED LINE

4236772

4236772

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/03/2020  
TIME 15:53

VEHICLE NO SLH3290A

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

Inchcape

Scanned by CamScanner