

Shirley Hiew (LKK Auto)

From: Kenneth Kong (LKKAuto)
Sent: Friday, 17 April 2020 11:04 am
To: Shirley Hiew (LKK Auto)
Subject: Fw: GBA 7735M

LSump \$2600.00 confirmed.
Tailgate bent price change \$2398
Rear taillamp @\$288.00
Spare tyre bracket bent \$336.00

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Sent: Wednesday, 15 April 2020 4:28 PM
To: Autoexcel Engineering Pte Ltd <aeexcel@singnet.com.sg>
Subject: Re: SCR8398U - GIA

Hi Ryan, GBA 7735 L/Sump \$2600.00, 3days. Kenneth

From: Autoexcel Engineering Pte Ltd <aeexcel@singnet.com.sg>
Sent: Tuesday, 7 April 2020 1:52 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: FW: SCR8398U - GIA

Hi Kenneth,

Attach GIA report SCR 8398 U

Thank you & Regards

Ryan Soh (Manager)
Handphone : 93825367 / 90030857 .
DirectLine : 64535654
Fax : 64591698

From: Danny Ong <danny.ong@mbmwheelpower.com.sg>
Sent: Tuesday, 7 April 2020 1:04 PM
To: 'Autoexcel Engineering ' <aeexcel@singnet.com.sg>
Subject: SCR8398U - GIA

Ryan

Enclosed GIA Report

Best regards,

Danny Ong / Claims Advisor



T 6262 8888 | **F** 6452 5333 | **M** 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg