

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GRE	AT AMERICAN IN	SURANCE COMPANY	Ref : CS/GAI20004682/Qyd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date: 21-04-2020	
			Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 6463M	Veh. Inspected	GBH 708B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CLMOMVC000003741	Excess (\$)	0.00
	Assign From	SHERY WONG	Assign Date	30/03/2020
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JN1SC2F24Z0860979	Colour	SILVER
	Odometer	39998	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DURATURN	6 mm
	L/H Front Tyre	195 R15C	DURATURN	6 mm
	R/H Rear Tyre	165 R13C	CONDOR	5/5 mm
	L/H Rear Tyre	165 R13C	CONDOR	5/5 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	22/10/2019	Inspection Date	03/04/2020
	Survey held at	PAN PACIFIC-56 LOYANG WAY	′#06-07	
	Repairer	-		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			