

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang

Date: 03 Apr 2020

Preliminary Advice

Vehicle No	: SJN4210S	Accident Date	: 27/03/2020
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPCSNA00014622001
Assignment Date	: 01/04/2020	Excess	: S\$0.00
Date of Inspection	: 31/3/2020	Est. Duration of Repair	: 10
Inspection At	: SM AUTOMOTIVE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,820.14 (incl.supplementary \$12,430.00)
Revised Amount	:S\$	15,107.24
Check Items (Estimated)	:S\$	1,262.80
Total	:S\$	16,370.04 (incl.supplementary \$12,430.00)
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	22,868.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,132.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on Lump Sum basis.