



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20004720/Kea3s2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 18-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6598L	Veh. Inspected	SLU 8113C
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001566MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	24/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102066468	Colour	METALLIC MAROON
Odometer	158948	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	YOKOHAMA	2 mm
L/H Front Tyre	215/60 R17	YOKOHAMA	2 mm
R/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm
L/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2020	Inspection Date	30/03/2020
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------