

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 01 Apr 2020

## **Preliminary Advice**

Vehicle No	: SMP4083X	Accident Date	: 27/03/2020
Make	: AUDI A4	Policy No.	: 1900167425
Assignment Date	: 31/03/2020	Excess	: S\$0.00
Date of Inspection	: 31/03/2020	Est. Duration of Repair	: 11 days
Inspection At	: Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,625.00
Revised Amount	:S\$	29,553.00
Check Items (Estimated)	:S\$	13,329.00
Total	:S\$	42,882.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	64,487.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,513.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :