

VEHICLE NO: SFB 3344G

VEHICLE NO: SFB 3344G


LKK Auto Consultants hence notify the **Repairer** of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:



CHEVROLET

Repair Estimate

Date : 30/03/2020

Steve (LKK) OD - 1st A/L (RM)
S122 8313 Excess ?
2/4/20, 2.99pm
P/P
Ry DL Ry
4 dyl

Reference: CHEVROLET
Make: ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE.: SFB3344G
CHASSIS NO.: KL1YA7589HK612693
ENGINE NO.: B14NET163570758

Name of insured.: LATA A KALWANI
Date of accident.: 27/03/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description		Price (SGD)
1	1	FRT BONNET X R	X	\$ 1,958.00
2	10	FRT FENDER WHEELARCH CLIP / M	✓ 26.00	\$ 65.00
3	10	FRT FENDER INNERSHIELD CLIP X NN	X	\$ 65.00
4	1	FRT FENDER RH / M	✓	\$ 1,243.00
5	1	FRT FENDER BRACKET RH X NN	X	\$ 128.00
6	1	FRT FENDER INNERSHIELD RH X NN	X	\$ 268.00
7	1	FRT FENDER TOP GARNISH RH X NN	X	\$ 88.00
8	1	FRT FENDER WHEELARCH GARNISH RH / M	✓	\$ 152.00
9	1	FRT BUMPER / RR	✓	\$ 1,406.00
10	1	FRT BUMPER LOWER / M	✓	\$ 516.00
11	1	FRT BUMPER LOWER GARNISH(silver colour) X NN	X	\$ 333.00
12	10	FRT BUMPER CLIP / RL	✓ 26.00	\$ 65.00
13	1	FRT BUMPER SIDE RETAINER LH, SUPPORT X NN	X	\$ 133.00
14	1	FRT BUMPER SIDE RETAINER RH, SUPPORT / RR	✓	\$ 133.00
15	1	FRT BUMPER BRACKET LH, GUIDE X NN	X	\$ 111.00
16	1	FRT BUMPER BRACKET RH, GUIDE X NN	✓	\$ 111.00
17	1	FRT BUMPER SPONGE X Cured	✓	\$ 263.00
18	1	FRT BUMPER REINFORCEMENT, IMPACT BAR X NN	X	\$ 927.00
19	1	FRT BUMPER LOGO / M	✓	\$ 158.00
20	1	FRT BUMPER LOW LIP X NN	X	\$ 173.00
21	1	FRT BUMPER FOG LAMP COVER RH X NN	X	\$ 113.00
22	1	FRT BUMPER FOG LAMP RH X Cured	✓	\$ 330.00
23	1	FRT GRILLE TOP X NN	X	\$ 243.00
24	1	FRT GRILLE TOP COVER X NN	X	\$ 131.00
25	1	FRT GRILLE LOW X NN	X	\$ 311.00
26	1	RH HEADLAMP / RL	✓	\$ 983.00
27	1	FRT WHEELHOUSE MEMBER RH X NN	X	\$ 651.00
28	1	A/C CONDENSER X NN	X	\$ 875.00
29	1	A/C CONDENSER TOP AIR GUIDE X NN	X	\$ 150.00
30	1	FRT KNUCKLE ARM RH X NN	X	\$ 417.00
31	1	FRT WHEEL BEARING RH X Cured	✓	\$ 587.00
32	1	FRT LOW ARM RH X NN	X	\$ 928.00
33	1	FRT SHOCK ABSORBER RH X NN	X	\$ 443.00
34	1	FRT STABILIZER LINK RH X NN	X	\$ 142.00

INE MOTORS PTE LTD

11 Close, Alpine Centre, Singapore 408604

is : Tel: (65) 6511 3033 Fax: (65) 6511 3038

Service : Tel: (65) 6511 3022 Fax: (65) 6456 3700

Parts : Tel: (65) 6511 3023 Fax: (65) 6458 9500

www.alpinemotors.sg

www.chevrolet.com.sg

35	1	FRT RIM RH / (N)			
36	1	Frt RH Door X	✓	\$	898.00
37	1	Frt RH Door Black Sticker X	NN	X	\$ 1,700.00
38	1	Frt RH Door Protector X	NN	X	\$ 196.00
			NN	X	\$ 151.00

Parts Total: \$ 17,545.00

Less 10%: \$ 1,754.50

Total : \$ 15,790.50

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. 550	\$ 2,750.00	1100 ✓
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT WHEELHOUSE PANEL RH, FRT FENDER RH, FRT DOOR RH 500	\$ 3,000.00	1500 ✓
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	80 ✓
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 220.00	X
5	To remove and refit radiator and conduct pressure test	\$ 120.00	X
6	To remove and replace RHF under carriage parts	\$ 550.00	275 ✓
7	To conduct 4 wheel alignment	\$ 180.00	120 ✓
8	To conduct reset of engine light on	\$ 350.00	X

Labour Total : \$ 7,290.00

Others

No.	Other Description	Price (SGD)	
1	FRT NUMBER PLATE	\$ 65.00	X
2	FRT TYRE RH TN	\$ 300.00	✓

Other Total: \$ 365.00

TOTAL: \$ 23,445.50
GST (7%): \$ 1,641.19

GRAND TOTAL : \$ 25,086.69

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurveyed
15/04/20 Adrian G