

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Dear Sirs :

RE : ESTIMATE COST FOR BMW 640I - SJA5555J
ACCIDENT INVOLVING SJA5555J & SJF950H ON 28/03/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper	1pc	repair
2	Front headlamp o/s. <i>SCA ✓</i>	1pc	\$ 7,800.00
3	Front bumper sensor <i>SCA ✓</i>	1pc	\$ 520.00
			\$ 8,320.00
	Less 5%		\$ (416.00)
			\$ 7,904.00
	<u>Labour Charge & Misc</u>		
	To remove, repair, replace & install damaged parts.	}	\$ 350.00 200
	To R & R sensor wiring.		\$ 100.00 80
	To R & R wiring.		\$ 60.00 30
	To putty & spray painting.		\$ 400.00 250
	Total		\$ 8,814.00

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

15/4/20 - ENVIRED TO PASUL

PASUL

Up 90010066

3 days

P/P

15/04/2020 @ 11:10

Repair before repair