



TP CLAIM  
CHINA TAIPING  
LKK-Taufikh

VEHICLE NO : SKT5832Y

MODEL : MIT/LANCER EX 1.6 4A/T

WIP : 52686

|                  |      |                         |
|------------------|------|-------------------------|
| Material         | : \$ | <u>1,128.00</u>         |
| Labour           | : \$ | <u>1,380.00</u>         |
| Sub-Total        | : \$ | <u>2,508.00</u>         |
| Less 2% Disc     | : \$ | <u>—</u>                |
| Less Excess      | : \$ | <u>—</u>                |
| Total            | : \$ | <u>2,508.00</u>         |
| GST 7%           | : \$ | <u>175.56</u>           |
| Grand Total      | : \$ | <u>2,683.56</u>         |
| Finalise By/Date | :    | <u>Army on 09/07/20</u> |

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

\* TP VEHICLE NO: SJQ8981H

\* claim loss of RENTAL.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

**THIS IS NOT AN OFFICIAL TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address  |  | Owner Name & Vehicle Info   |   |
|---|--|---|---|
| Tan Wei-wen Paul (chen Weiwen,<br>12 Ang Mo Kio Avenue 2<br>#07-16<br>Singapore 567697<br>Contact No Mobile: 81336339<br>30/06/2020 |  | Cust No/Name<br>Reg No/Reg Date<br>Date In/Mileage<br>Chassis/Package<br>Engine No<br>Make/Model<br>Colour/Trim | KCV07257/Tan Wei-Wen Paul (Chen Weiwen,P<br>/ 16/06/2015<br>30/06/2020/ 102564<br>JMYSRCY1AFU00471C<br>4A92BX6166<br>MIT/LANCER EX 1.6 GLS 4A/T (F05)<br>W03 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator             | WIP No |
|------------|-------|-------------------|-----|----------------------|--------|
| CTP00040   | Cash  | 09/07/2020/ 11:39 | TLE | 884 / Lauro Songcuan | 52686  |

| Description of Goods / Services   | Qty  | Unit Price | Disc% | Amount   |
|---|------|------------|-------|----------|
| E PNT88000<br>RENEW REAR BUMPER   |      |            |       | 550.00 ✓ |
| E PNT98000<br>SPRAY PAINT REAR BUMPER   |      |            |       | 420.00 ✓ |
| A 54900099<br>CHECK WIRING & CHASSIS ELECTRICAL SYSTEM  |      |            |       | 30.00 ✓  |
| A 10028901<br>TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST            |      |            |       | 200.00 ✓ |
| E PNT88000<br>REMOVE AND REFIT REVERSE SENSOR   |      |            |       | 80.00 ✓  |
| M SUNDRY<br>SUNDRIES  |      |            |       | 20.00 ✓  |
| S SPECIALISTJOB<br>SUPPLY REAR LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)                           |      |            |       | 80.00 ✓  |
| X FACE,RR BUMPER R  | 1.00 | 861.00     | 00.00 | 861.00 ? |
| X BRKT,R/BMPR FACE SUPT,LH ✓  | 1.00 | 17.00      | 00.00 | 17.00 ✓  |
| X BRKT,R/BMPR FACE SUPT,RH ✓  | 1.00 | 17.00      | 00.00 | 17.00 ✓  |
| X REINFORCEMENT,RR BUMPER X   | 1.00 | 233.00     | 00.00 | 233.00 ? |
| Z TEXT<br>TP CLAIM CHINA TAIPING - SJQ8981H<br>SURVEY: TAUFIKH 19.05.2020<br>DOA: 31.03.2020<br>03 DAYS |      |            |       |          |

Guarantee Your Warranty, Maintain with Cycle & Carriage!

|                 |          |               |          |
|-----------------|----------|---------------|----------|
| Parts           | 1,128.00 | Nett          | 2,508.00 |
| Labour          | 1,280.00 | 7% GST on     | 175.56   |
| Standard Menu   | 0.00     |               |          |
| Specialist Job  | 80.00    | Total Payable | 2,683.56 |
| Diagnostics Job | 0.00     |               |          |
| Sundry/Others   | 20.00    |               |          |
| Total(w/o GST)  | 2,508.00 |               |          |

This is not an official tax invoice.  
This is a computer generated document, no signature is required.