



## TRANS EUROKARS PTE LTD



## ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L  
64 CECIL STREET  
#04-#05 IOB BUILDING  
SINGAPORE 049711

NAME : Ms Tang Jing Jing  
ADDRESS : No, 27A Jalan Chengkek  
Singapore 369249  
TEL : 98211047

WIP : 25032  
EXCESS :  
DATE: 23-Mar-20

ATTN : MOTOR CLAIMS  
FAX :

*not Authorized*  
*26m*  
*to be before 2017*  
*4 days*  
*8509930*

VEH NO : SJJ1121G DATE IN : CONTACT PERSON : Ronald 63957875  
CHASSIS NO : JM6GL1031H0124169 MILEAGE : TYPE OF CLAIM : THIRD PARTY CLAIM  
MODEL : MAZDA6 DATE REG.: 29-Sep-17 POLICY NO. :

## NATURE OF WORKS

## Parts Description

NO	QTY	REVISED	PRICES
1	FRONT BUMPER <i>cu7</i> 1	MGMV8-50-031CBB ✓	\$ 1,211.90 ✓
2	RETAINER RHS <i>11</i> 1	MGHP9-50-0T1B X	\$ 17.10 X
3	CHROME RHS, FOGLAMP <i>11</i> 1	MG46L-50-C12 X	\$ 101.90 X
4	CLIP, FRONT BUMPER <i>111</i> 6	MC274-50-133 ✓	\$ 22.20 ✓
5	FASTENER, FRONT BUMPER <i>111</i> 2	MB45A-56-146A ✓	\$ 6.00 ✓
6	GROMMET, FRONT BUMPER <i>111</i> 2	MGHP9-50-0Z5 ✓	\$ 5.80 ✓
7	FASTENER, FRONT BUMPER <i>111</i> 6	MGD7A-50-EA1 ✓	\$ 19.20 ✓
8	RIVET, FRONT BUMPER <i>111</i> 6	MGHP9-50-355 ✓	\$ 29.40 ✓
9	RIVET, FRONT BUMPER <i>111</i> 8	MS51S-51-833 ✓	\$ 32.00 ✓
10	FRONT WHEEL RIM RHS <i>Deep cu7</i> 1	M9965-20-7590 ✓	\$ 1,497.80 ✓
TOTAL PARTS			\$ 2,943.30
TOTAL PARTS COST			\$ 2,943.30

## Labour Description

1	MZ-BR-FRONT1	TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i> \$ 1,320.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.	<i>945</i> \$ 1,260.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.	<i>180</i> NETT \$ 330.00
4		TO SUPPLY 1 PC TIRE.	<i>11</i> X \$ 480.00
5	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	<i>117X</i> NETT \$ 120.00

6	MZ-BR-WHEAL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	200	NETT	\$ 560.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11X		\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150		\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	100	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 5,020.00
TOTAL PARTS	\$ -	\$ 2,943.30
TOTAL	\$ -	\$ 7,963.30
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: