



ESTIMATE TO REPAIR

VEHICLE NO. : SLT 158 G
 MAKE : HONDA
 MODEL : SHUTTLE 1.5G CVT SENSING
 YEAR : 2019
 CHASSIS NO : GK82101309

SURVEYOR NAME : <i>Kenneth (LKK)</i>
DATE OF SURVEY : <i>02.06.2020</i>
TIME OF SURVEY :

DATE : 01-Apr-20
 DATE OF ACCIDENT : 20-Mar-20
 THIRD PARTY REF : GZ 6707 K / CHINA TAIPING

No.	Parts Description / Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear LH Door			<i>Ad/way</i>	\$ 799.50 ✓
1 pc	Rear LH Door frame Tape				\$ 18.50 ✓
	Less 20%				\$ 818.00
					\$ 163.60
					\$ 654.40
	To Putty & Spray <i>Painting</i>				\$ 300.00 <i>22cl</i>
	To transfer Door Fitting				\$ 50.00 ✓
	To Anti Rust				\$ 50.00 <i>3cl</i>
	Labour Charges				\$ 250.00 <i>20cl</i>
				<i>Not with hold the survey B4 painting 2 days</i>	
TG-TH/-	TOTAL				\$ 1,304.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd