



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20004899/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA

Date : 19-08-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 3114E	Veh. Inspected	SKQ 3972E
Policy No.	VFX/P2070284	Coverage (\$)	0.00
Claim No.	S0M02KTN	Excess (\$)	0.00
Assign From		Assign Date	06/04/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6 SP (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JM6GJ1071F0144652	Colour	GREY
Odometer	58670	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/04/2020	Inspection Date	06/04/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------