



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20001167/Htf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

ATTN : MAVIS CHEW

Date : 15-04-2020



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SGZ 7923X	<b>Veh. Inspected</b>	FBA 991K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	7096227552SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MAVIS CHEW	<b>Assign Date</b>	06/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA CB400	<b>c.c</b>	399
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2006
<b>Chassis No.</b>	JH2NC39945M100285	<b>Colour</b>	SILVER / BLUE
<b>Odometer</b>	169180	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	120/60Z R17	MICHELIN	5 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	160/60Z R17	MICHELIN	5 mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/01/2020	<b>Inspection Date</b>	21/01/2020
<b>Survey held at</b>	10 KAKI BUKIT ROAD 2 #01-36		
<b>Repairer</b>	O.M MOTOR SERVICES		

### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
- B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>4 Working Days</b>
--	-----------------------