

COMFORTDELGRO ENGINEERING

Our Job Ref No 305391801

Date : 09.04.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

REF: CS/EQ/20004943
/FTFS

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHC8133L CTPL

01.04.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ INS --- SLK3585J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,350.00
Final Lumpsum Repair cost \$1,350.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : RAM

Date : 13/04/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>cut / DEF</i>	20.00	0.00	*1,106.00 F
2	10		*REAR BUMPER CLIPS <i>rec</i>	20.00	0.00	*22.00 F
3	1		*REAR BUMPER UNDER COVER <i>Sc</i>	20.00	0.00	*228.00 F
4	1		*REAR BUMPER SIDE BRACKET LH <i>xm</i>	20.00	0.00	*35.60 F
5	1		*REAR BUMPER REVERSE SENSOR <i>1xm</i>	0.00	0.00	*135.70 F
6	1		*REAR BUMPER RUBBER MAT <i>na</i>	0.00	0.00	*50.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	1,577.30
- List Item Discount on L Items (\$\$)	278.32
Total Parts (\$\$)	1,298.98

ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$1280 350.00
2	SPRAY PAINTING CHARGE	New	\$200 250.00
3	REMOVE/REFIX REVERSE SENSOR	New	\$60 80.00
Gross Labour Cost (\$\$)			680.00

ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

knownedged by Repairer

Signature:

Date:

Ram (LKK)
3/4/2020 1515
Ravagum@Ravagum.com
88622778
AD + repairer
LIS
2 days in days

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$280 350.00
2	SPRAY PAINTING CHARGE	New	\$200 250.00
3	REMOVE/REFIX REVERSE SENSOR	New	\$60 80.00
Gross Labour Cost (\$\$)			680.00

ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ITEM : \$1134.80

Labour : \$540

Total : \$1674.80

L/S : \$1350/=

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

knownedged by Repairer

Signature:

Date:

Ram (LKK)
3/4/2020 1515
Ravesh@Ravesh.com
88622778
ad + repair
L/S
Super days