



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20004948/Qyf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-06-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 2038Y	Veh. Inspected	SLD 4477T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD20001384/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/04/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11112217	Colour	SILVER
Odometer	77027	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2020	Inspection Date	06/04/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
 B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--------------------------------------------	-----------------------