



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	BP-SUBLET TO REPLACE FLOOR PANEL, RH REAR QUARTER PANEL				3520.00
2	S	BP-SUBLET TO RESPRAY FLOOR PANEL AND RH REAR QUARTER PANEL				1320.00
3	1	H74201-E0021 PANEL SUB-ASSY, FR A bt	1.00	75.20		75.20
4	2	H74630-E0020 GRIP ASSY, DOOR ASSI bt	1.00	118.90		118.90
5	3	HS8501-E0020 LINK SUB-ASSY, FR WI bt	1.00	157.90		157.90
6	4	H57035-E0010 PANEL SUB-ASSY, FR S bt	1.00	355.40		355.40
7	5	HS5703-E0010 SUPPORT SUB-ASSY, FR bt	1.00	322.00		322.00
8	6	HS5571-51010 STAY, FR CORNER PANEL nec	1.00	19.00		19.00
9	7	HS5370-52460 BRACKET SUB ASSY, FR bt	1.00	142.90		142.90
10	8	HS530C-E0010 SUPPORT SUB-ASSY, ST bt	1.00	339.20		339.20
11	9	H67875-E0010 WEATHERSTRIP, FR DOOR, NO.4 RH nec	1.00	81.00		81.00
12	0	H69810-E0051 REGULATOR ASSY, DOOR bt	1.00	821.20		821.20
13	1	H55311-E0280 HOUSING, INSTR CLUSTE de	1.00	1193.60		1193.60
14	2	H53803-E0010 REINFORCE SUB-ASSY bt	1.00	261.80		261.80
15	3	HS8741-51680 CABLE, CONTROL nw	1.00	103.40		103.40
16	4	H61131-E0120 PILLAR, FR BODY, UPR bt	1.00	603.40		603.40
17	5	H61611-E0030 PANEL, QUARTER RH bt	1.00	1006.40		1006.40
18	6	H65621-E0010 PANEL, SIDE GATE bt	1.00	107.40		107.40

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4223282

TO SECURITY GUARD

4223282

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/10/2020
TIME 15:34

VEHICLE NO

XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4-Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
19	7	HS7420-61780 GRIP SUB ASSY, INSIDE bt	1.00	258.80		258.80
20	8	H55108-E0011 BRACE SUB-ASSY, PEDAL SUPPORT TO CC bt	1.00	532.30		532.30
21	9	H55835-E0070 DUCT, HEATER TO REGI cra	1.00	253.30		253.30
22	0	H55990-E0030 NOZZLE ASSY, DEFROST bt	1.00	267.30		267.30
23	1	H87213-E0060 DUCT, HEATER TO FOOT cra	1.00	48.50		48.50
24	2	H61415-E0011 EXTENSION, ROCKER, o bt	1.00	260.50		260.50
25	3	H61135-E0030 REINFORCEMENT, FR BODY PILLAR, UPR bt	1.00	80.50		80.50
26	4	H61108-E0013 REINFORCEMENT SUB-ASSY, FR PLR, LWF bt	1.00	239.30		239.30
27	5	H61106-E0021 PILLAR SUB-ASSY, FR, RH bt	1.00	260.50		260.50
28	6	H61163-E0031 PILLAR, FR BODY, LWR INNER RH bt	1.00	316.20		316.20
29	7	HS1661-02030 TANK ASSY, RESERVE de	1.00	429.10		429.10
30	8	H81110-E0682 HEADLAMP ASSY cra	1.00	750.30		750.30
31	9	HS5530-12091 PANEL SUB ASSY, INSTR bt	1.00	1240.80		1240.80
32	0	H55712-E0390 PANEL, COWL TOP, OUT de	1.00	677.60		677.60
33	1	H55330-E0061 REINFORCEMENT ASSY, bt	1.00	849.00		849.00
34	2	HS8338-02331 SWITCH ASSY, PRESS nw	1.00	70.50		70.50
35	3	H45286-E0070 COVER, STEERING COLUMN, UPR de	1.00	36.50		36.50
36	4	H45287-E0070 COVER, STEERING COLUMN, LWR de	1.00	57.70		57.70
37	5	HS4529-61010 BOOTS, STRG COLUMN LW nec	1.00	20.00		20.00
38	6	H45252-E0010 TUBE, STEERING COLUM nec	1.00	80.00		80.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE


4223283

4223283

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 26/10/2020
TIME 15:34VEHICLE NO
XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
39	7	H17700-E0C10 CLEANER ASSY, AIR de /	1.00	1436.60		1436.60
40	8	H87010-E0171 UNITASSY, AIR CONDIT cra /	1.00	2126.20		2126.20
41	9	H87130-E0120 BLOWER ASSY cra /	1.00	838.50		838.50
42	0	HS3132-11110 PAD, PEDAL cut /	1.00	14.30		14.30
43	1	HS8946-01410 SENSOR nw /	1.00	249.30		249.30
44	2	H51773-E0140 COVER, STEP PLATE, RH cra /	1.00	332.00		332.00
45	3	HSZ950-39347 RETAINER nec /	4.00	3.30		13.20
46	4	HSZ950-39187 RETAINER nec /	3.00	2.10		6.30
47	5	HS51B1-E0010 BOLT, CAB MOUNTING nec /	2.00	65.70		131.40
48	6	HS5278-71100 NUT nec /	2.00	9.50		19.00
49	7	HS8724-21120 DUCT, HEATER TO FOOT cra /	1.00	154.30		154.30
50	8	H58241-E0040 BRACKET, FR SEAT MOU bt /	1.00	1529.10		1529.10
51	9	H58517-E0020 PAD, HEEL cut /	1.00	88.30		88.30
52	0	HS4735-91550 BRACKET, PIPE, JOINT bt /	1.00	77.50		77.50
53	1	HS4701-E0290 BRACKET SUB-ASSY, TU bt /	1.00	169.20		169.20
54	2	HS500Q-E0040 BRACKET SUB-ASSY, TI bt /	1.00	525.50		525.50
55	3	HS5032-E0051 LEVER SUB-ASSY, TILT bt /	1.00	3423.40		3423.40
56	4	H51701-E0300 COVER SUB-ASSY, SIDE de /	1.00	1101.90		1101.90
57	5	H45302-E0071 BRACKET SUB-ASSY, ST bt /	1.00	944.40		944.40
58	6	HS50B0-E0190 ABSORBER ASSY, CAB R bt /	1.00	262.80		262.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4223284

TO SECURITY GUARD

4223284

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/10/2020
TIME 15:34

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
59	7	HS50C0-E0020 SPRING ASSY, CAB FR nec	1.00	394.90		394.90
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 26,275.50 Labour 0.00 Materials 4,840.00 Lubrication/Fluid 0.00 Others 0.00	31,115.50 GST 7.00% 2,178.09 Less 0.00 Amount Due 33,293.59

PLEASE TEAR ALONG PERFORATED LINE

4223285

TO SECURITY GUARD

4223285

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 26/10/2020
TIME 15:35

VEHICLE NO

XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Inchcape