



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail					
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518					
		Document No						
		0						
		Document Date						
		26/10/2020						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L	
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	S	BP-SUBLET (A) TO REPLACE FLOOR PANEL, RH REAR QUARTER PANEL						3520.00
2	S	BP-SUBLET (A) TO RESPRAY FLOOR PANEL AND RH REAR QUARTER PANEL						1320.00
3	1	H74201-E0021	PANEL SUB-ASSY, FR A bt		1.00	75.20		75.20
4	2	H74630-E0020	GRIP ASSY, DOOR ASSI bt		1.00	118.90		118.90
5	3	HS8501-E0020	LINK SUB-ASSY, FR WI bt		1.00	157.90		157.90
6	4	H57035-E0010	PANEL SUB-ASSY, FR S bt		1.00	355.40		355.40
7	5	HS5703-E0010	SUPPORT SUB-ASSY, FR bt		1.00	322.00		322.00
8	6	HS5571-51010	STAY, FR CORNER PANEL nec		1.00	19.00		19.00
9	7	HS5370-52460	BRACKET SUB ASSY, FR bt		1.00	142.90		142.90
10	8	HS530C-E0010	SUPPORT SUB-ASSY, ST bt		1.00	339.20		339.20
11	9	H67875-E0010	WEATHERSTRIP, FR DOOR, NO. 4 RH nec		1.00	81.00		81.00
12	0	H69810-E0051	REGULATOR ASSY, DOOR bt		1.00	821.20		821.20
13	1	H55311-E0280	HOUSING, INSTR CLUSTE de		1.00	1193.60		1193.60
14	2	H53803-E0010	REINFORCE SUB-ASSY bt		1.00	261.80		261.80
15	3	HS8741-51680	CABLE, CONTROL nw		1.00	103.40		103.40
16	4	H61131-E0120	PILLAR, FR BODY, UPR bt		1.00	603.40		603.40
17	5	H61611-E0030	PANEL, QUARTER RH bt		1.00	1006.40		1006.40
18	6	H65621-E0010	PANEL, SIDE GATE bt		1.00	107.40		107.40
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Materials				
				Lubrication/Fluid				
				Others				
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

4223282

TO SECURITY GUARD

4223282

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.


DATE 26/10/2020
TIME 15:34

VEHICLE NO

XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
19	7	HS7420-61780 GRIP SUB-ASSY, INSIDE bt	1.00	258.80		258.80
20	8	H55108-E0011 BRACE SUB-ASSY, PEDAL SUPPORT TO CC bt	1.00	532.30		532.30
21	9	H55835-E0070 DUCT, HEATER TO REGI cra	1.00	253.30		253.30
22	0	H55990-E0030 NOZZLE ASSY, DEFROST bt	1.00	267.30		267.30
23	1	H87213-E0060 DUCT, HEATER TO FOOT cra	1.00	48.50		48.50
24	2	H61415-E0011 EXTENSION, ROCKER, o bt	1.00	260.50		260.50
25	3	H61135-E0030 REINFORCEMENT, FR BODY PILLAR, UPR bt	1.00	80.50		80.50
26	4	H61108-E0013 REINFORCEMENT SUB-ASSY, FR PLR, LWF bt	1.00	239.30		239.30
27	5	H61106-E0021 PILLAR SUB-ASSY, FR, RH bt	1.00	260.50		260.50
28	6	H61163-E0031 PILLAR, FR BODY, LWR INNER RH bt	1.00	316.20		316.20
29	7	HS1661-02030 TANK ASSY, RESERVE de	1.00	429.10		429.10
30	8	H81110-E0682 HEADLAMP ASSY cra	1.00	750.30		750.30
31	9	HS5530-12091 PANEL SUB ASSY, INSTR bt	1.00	1240.80		1240.80
32	0	H55712-E0390 PANEL, COWL TOP, OUT de	1.00	677.60		677.60
33	1	H55330-E0061 REINFORCEMENT ASSY, bt	1.00	849.00		849.00
34	2	HS8338-02331 SWITCH ASSY, PRESS nw	1.00	70.50		70.50
35	3	H45286-E0070 COVER, STEERING COLUMN, UPR de	1.00	36.50		36.50
36	4	H45287-E0070 COVER, STEERING COLUMN, LWR de	1.00	57.70		57.70
37	5	HS4529-61010 BOOTS, STRG COLUMN LW nec	1.00	20.00		20.00
38	6	H45252-E0010 TUBE, STEERING COLUM nec	1.00	80.00		80.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4223283

TO SECURITY GUARD

4223283

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME
26/10/2020
15:34

VEHICLE NO

XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/10/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
39	7	H17700-E0C10	1.00	1436.60		1436.60
40	8	H87010-E0171	1.00	2126.20		2126.20
41	9	H87130-E0120	1.00	838.50		838.50
42	0	HS3132-11110	1.00	14.30		14.30
43	1	HS8946-01410	1.00	249.30		249.30
44	2	H51773-E0140	1.00	332.00		332.00
45	3	HSZ950-39347	4.00	3.30		13.20
46	4	HSZ950-39187	3.00	2.10		6.30
47	5	HS51B1-E0010	2.00	65.70		131.40
48	6	HS5278-71100	2.00	9.50		19.00
49	7	HS8724-21120	1.00	154.30		154.30
50	8	H58241-E0040	1.00	1529.10		1529.10
51	9	H58517-E0020	1.00	88.30		88.30
52	0	HS4735-91550	1.00	77.50		77.50
53	1	HS4701-E0290	1.00	169.20		169.20
54	2	HS500Q-E0040	1.00	525.50		525.50
55	3	HS5032-E0051	1.00	3423.40		3423.40
56	4	H51701-E0300	1.00	1101.90		1101.90
57	5	H45302-E0071	1.00	944.40		944.40
58	6	HS50B0-E0190	1.00	262.80		262.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4223284

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME
26/10/2020
15:34

4223284

VEHICLE NO
XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

ESTIMATE

Account Detail		Account No		Customer Detail				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1		M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518				
		Document No						
		0						
		Document Date						
		26/10/2020						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
19	KAS	FS1EKND	23/01/2020	XE5495L	11176	54615	72/OD/XE5495L	
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On			
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
59	7	HS50C0-E0020 (A) SPRING ASSY, CAB FR nec			1.00	394.90		394.90
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts		31,115.50		
				Labour	26,275.50	GST 7.00%	2,178.09	
				Materials	0.00	Less	0.00	
				Lubrication/Fluid	4,840.00			
				Others	0.00			
				0.00		Amount Due	33,293.59	

PLEASE TEAR ALONG PERFORATED LINE

4223285

TO SECURITY GUARD

4223285


PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/10/2020
TIME 15:35

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape