

ASS. REC. BY:

REF:

C72 / CTJ 20004958 / Kyp3e2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 875k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 2124R Yr Regn: 10, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Toy Wish c.c. 1798Colour: N. Gold A/C: Insured / Std / NI / NASp. Reading: 320PS T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JDGG20W90J007792Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD / VRim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 2/4/20 D.O.I. 4/4/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

CLOSE: 11/8/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

916C

Vehicle Details

Vehicle No.:

SLT2124R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

03 Apr 2020

Vehicle Make:

TOYOTA

Vehicle Model:

WISH 1.8 CVT

Primary Colour:

Beige

Manufacturing Year:

2017

Engine No.:

2ZR0A06126

Chassis No.:

JTDGG20W90J007792

Maximum Power Output:

105.0 kW (140 bhp)

Open Market Value:

\$19,955.00

Original Registration Date:

23 Oct 2017

First Registration Date:

23 Oct 2017

Transfer Count:

1

Actual ARF Paid:

\$19,955.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

22 Oct 2027

PARF Rebate Amount:

\$14,966.00

Intended COE Rebate Details

COE Expiry Date:

22 Oct 2027

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$49,000.00

COE Rebate Amount:

\$36,327.00

Total Rebate Amount:**\$51,293.00**

The information contained herein is correct as at 03 Apr 2020

OK



Toyota Wish 1.8A

\$80,800

\$9,560 /yr

30-Aug-2017

1,798 cc

65,567 km

MPV

Available

1 Owner, Flexible Loan With Low Interest Rate Owner Well Maintained By One Owner Agent Unit, Excellent Condition Call To View Now!

Posted: 01-Apr-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A

\$79,200

\$9,120 /yr

16-Nov-2017

1,798 cc

30,000 km

MPV

Available

Serviced And Maintained By Borneo Motors And Under Warranty, 1 Careful Owner, Very Beautiful Unit, 90% Loan Available, No Gamick...

Posted: 01-Apr-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A

\$81,800

\$9,550 /yr

09-Oct-2017

1,798 cc

43,000 km

MPV

Available

1 Owner, Low Mileage Done, Immaculate Condition, 1 Of The Most Reliable MPV In The Market, \$0 Downpayment Scheme Available, Ca...

Posted: 01-Apr-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A

\$75,900

\$9,140 /yr

20-Jun-2017

1,798 cc

-

MPV

Available

1 Owner Only, Fully Maintained And 5 Year Warranty By Toyota Agent Borneo Motor Till Jun 2022 For Peace Of Mind, Bank And In Hous...

Posted: 01-Apr-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A

\$78,800

\$9,580 /yr

08-Jun-2017

1,798 cc

-

MPV

Available

Originally From Borneo Motors & Only 1 Previous Owner, Comes With Keyless Entry & Engine Start/Stop, Fully In Original Condition, The...

Posted: 30-Mar-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A Elegance

\$78,800

\$9,660 /yr

19-May-2017

1,798 cc

48,500 km

MPV

Available

Low Mileage Done, Well Maintained & Service By Agent Borneo Motors, Beautiful Paintwork With Clean & Near Interior, 2.08% Bank Or L...

Posted: 30-Mar-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

Toyota Wish 1.8A X

\$73,800

\$9,020 /yr

19-May-2017

1,797 cc

26,000 km

MPV

Available

Low Monthly From \$6xx Only! Lowest Depreciation In The Market, Maintained By 1 Previous Owner Only, High Demanding MPV In The...

Posted: 30-Mar-2020

Tags: 2017 Toyota Wish, Toyota Wish, Toyota, Wish

EN

10:11 AM

4/3/2020

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
L/Ins & ?
Resurvey After Repair
16 days

Date : 02/04/2020

QUOTATION -THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SLT 2124 R
Model : TOYOTA WISH
Insured Ins: NTUC INCOME

Accident on : 02/04/2020

QTY	PARTICULARS	AMOUNT	SURVEYOR
	<u>Your Insurer Vehicle No : GBE 4302 C</u>		
1	TAILGATE <i>Bz</i>	\$ 1,480.00	✓
1	TAILGATE LOCK	\$ <i>Tm</i> 385.00	✓
1	TAILGATE LOCK SENSOR	\$ 335.00	?
1	TAILGATE TOP SPOILER	\$ 1,128.00	?
1	TAILGATE W/SCREEN <i>Shorten</i>	\$ 1,848.00	✓
1	TAILGATE W/SCREEN MOULDING <i>re</i>	\$ 280.00	✓
2	TAILGATE W/SCREEN INNER SIDE GARNISHES <i>Di 1</i>	\$ <i>Di</i> 776.00	✓
1	TAILGATE THIRD BRAKE LAMP	\$ 650.00	?
1	TAILGATE OUTER CHROME MOULDING <i>CM</i>	\$ 580.00	✓
1	TAILGATE OUTER CHROME INNER SWITCH	\$ 332.00	?
2	TAILGATE REFLECTORS <i>CM</i>	\$ 960.00	✓
1	TAILGATE TRIM BOARD <i>Bu</i>	\$ 540.60	✓
8	TAILGATE TRIM BOARD CLIPS <i>re</i>	\$ 32.00	✓
1	TAILGATE LOWER COVER	\$ 185.00	?
1	TAILGATE CENTER LOGO <i>re</i>	\$ 65.00	✓
1	TAILGATE VAVE MATIC EMBLEM <i>re</i>	\$ 68.00	✓
2	TAILGATE HINGES <i>R</i>	\$ 448.00	X
2	TAILGATE ABSORBERS	\$ 778.00	?
1	TAILGATE WIPER MOTOR <i>Tm</i>	\$ 685.00	✓
1	TAILGATE WIPER ARM <i>re</i>	\$ 323.00	✓
1	REAR FENDER LH <i>R</i>	\$ 840.00	X
1	REAR FENDER RH <i>Bu</i>	\$ 840.00	✓
2	REAR FENDER UNDERSHIELDS <i>re</i>	\$ 560.00	X
20	REAR FENDER UNDERSHIELD CLIPS	\$ <i>re</i> 70.00	X
2	REAR FENDER INNER SIDE TRIM BOARDS <i>ols Bu</i>	\$ 1,250.00	n/s ?
2	REAR FENDER INNER SIDE TRIM TOPS <i>ols Di</i>	\$ 780.00	✓
1	REAR FENDER QUARTER GLASS RH <i>Shorten</i>	\$ 588.45	✓
1	REAR FENDER QUARTER GLASS SIDE GARNISH	\$ <i>Di</i> 288.00	✓
1	REAR FENDER AIR DUCT RH <i>re</i>	\$ 212.00	✓
2	TAILLAMPS <i>n/s ?</i> <i>ols Bu</i>	\$ 1,380.00	✓
2	TAILLAMP PANELS <i>ols Bu</i>	\$ 448.00	✓
2	TAILLAMP SIDE CLIPS <i>ols re</i>	\$ 40.00	✓
2	TAILLAMP SOCKETS ASSY	\$ 596.00	?
2	TAILLAMP LOWER RETAINERS <i>ols Di</i>	\$ 280.00	✓
1	REAR DOOR RH	REPAIR	
1	REAR DOOR LOCK RH	\$ 480.00	?
1	END PANEL INNER	\$ <i>Bz</i> 480.00	✓
1	END PANEL OUTER	\$ <i>Bz</i> 552.00	✓
1	END PANEL TOP GARNISH	\$ 435.00	?

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

5	END PANEL TOP CLIPS	<i>RM</i>	\$ 25.00	✓
1	END PANEL TOP LATCH		\$ 78.00	?
1	END PANEL LATCH LOCK SWITCHES		\$ 288.00	?
1	FLOOR PANEL		\$ 980.00	?
1	FLOOR PANEL TOP BOARD		\$ 689.00	?
2	FLOOR PANEL SIDE BOARDS		\$ 880.00	?
1	FLOOR PANEL TOP INSULATOR		\$ 440.00	?
1	REAR SEAT RH		\$ 1,685.00	?
1	REAR SEAT LH		\$ 2,200.00	?
2	REAR SEAT BRACKETS		\$ 480.00	?
2	REAR SEAT CABLES	<i>RM</i>	\$ 680.00	X
1	REAR SEAT LOWER PANEL		REPAIR	
1	REAR SEAT LOWER GARNISH		\$ 552.00	?
1	ROOF UPHOLSTERY	<i>CM</i>	\$ 1,985.00	✓
1	ROOF PANEL		REPAIR	
1	SPARE TYRE CENTER SCREW		\$ 285.00	?
2	REAR CHASSIS		REPAIR	
1	REAR EXHAUST		\$ 685.00	?
1	REAR EXHAUST HEAT SHIELD	<i>R</i>	\$ 385.00	X
1	REAR EXHAUST MOUNTING		\$ 285.00	?
1	REAR BUMPER	<i>R</i>	\$ 840.00	✓
2	REAR BUMPER SIDE SCREWS		\$ 40.00	?
10	REAR BUMPER CLIPS	<i>RM</i>	\$ 35.00	✓
2	REAR BUMPER BRACKETS	<i>R</i>	\$ 260.00	✓
2	REAR BUMPER SIDE RETAINERS	<i>cls dir</i>	\$ 280.00	✓
2	REAR BUMPER REFLECTORS	<i>cls cm</i>	\$ 580.00	✓
2	REAR BUMPER SENSORS	<i>nd</i>	\$ 480.00	2005N
2	REAR BUMPER SENSOR CABLES		\$ 385.00	?
			\$ 37,500.05	
	Less 25%		\$ 9,375.01	
			\$ 28,125.04	
	S/NETT			
2TUBE	REAR W/SCREEN SEALANT	<i>RM</i>	\$ 140.00	605N
1 TUBE	REAR RH QUARTER GLASS SEALANT	<i>RM</i>	\$ 70.00	305N
1	REAR W/SCREEN SOLAR FLIM	<i>RM</i>	\$ 480.00	1201N
1	WIPER BLADE		\$ 220.00	?
1SET	REVERSE CAMERA ASSY		\$ 500.00	?
1SET	CAR DASHCAM 2 CHANNEL	<i>mit</i>	\$ 800.00	✓
1	SPARE TYRE	<i>R</i>	\$ 480.00	X
1	SPARE TYRE JACK		\$ 280.00	?
1	REAR TYRE LH	<i>R</i>	\$ 400.00	X
	S/NETT PARTS :		\$ 3,370.00	
	TOTAL PARTS :		\$ 31,495.04	

AE AUTO PTE LTD

160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 31,495.04	
	Towing Charges	REFER INV	
	Labour charges to do cutting , welding, replace repair, align adjust, remove refix rear accident affected area	\$ 2,200.00	1800h
	To replace and check on rear lamp wiring systems	\$ 200.00	301
	To replace dashcam, replace sensor and cables, replace reverse camera, replace solar flim (accessories)	\$ 300.00	1201
	Remove refix, replace side trims, garnish, trim board, upholstery car seat, seat belt etc for rear	\$ 500.00	1201
	To do anti rust	\$ 120.00	✓
	To do selant, seal gap, waterproofing , on cut welding affected area	\$ 250.00	801
	Transfer tailgate parts to another tailgate	\$ 100.00	601
	Replace rear w/screen	\$ 140.00	1201
	To do rear chassis body alignment	\$ 350.00	?
	To replace rear exhaust	\$ 180.00	601
	To do spray painting on accident affected area, inner outer .	\$ 2,000.00	1800h
	TOTAL LABOUR :	\$ 6,340.00	
	Total Parts & Labour :	\$ 37,835.04	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: