

### **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0356/2020/NS

Date : 2-Apr-20

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Dr Bhagwani Gopal Sanjeev

Address : 44 Keppel Bay Drive

#02-115

Singapore 098657

 Telephone
 : (HP) +65 91061972

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 1900103746

Vehicle No : SML 6937 R

Model Code : A4 Sedan 2.0 TFSI 8W

Model / Year : 30/5/2019 Engine No : CVK 077902

Chassis No : WAUZZZF47KA047225

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 31-Mar-20

Place of Accident : Furama City Centre Car Park

WIP: 34862

# **Premium Automobiles**

55 Uti-Road 1, Singapore 400000 Tel: 6,000 2023 Fax: 9A41 1383

Telefax

#### Estimated Labour Charges for Accident Vehicle, SML 6937 R

5/1	Nature of Jobs			Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage,	S/N	S	360.00	×
2	To dismantle rear bumper. To repair rear bumper, lhs rear fender and lhs rear door. Re-organise rear crash management components. Reinstall all parts removed.		\$	2,450.00	500
3	To respray rear bumper, lhs rear door and lhs rear fender.		S	2,800.00	550
4	To carry out diagnostic check.	S/N	s	192.00	
	TOTAL LABOUR CHARGES	1	\$	5,802.00	

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

## Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

Name

Surveyed Date

**Authorised Date** 

Excess Cost

Liability

Remarks

Tanpar 97445744

Ex: to readvise

Not introvae

Resny After syrin

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray pointing
- . To display damaged part(x) during resurvey
- · Parts prices are subject to confirmation
- . Thing party survey is on a "Without Projudice" basis
- No Regal modification(s) is allowed.
- Supplementary Itero(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dates

Johnny Boo Body Repair Manager

Allan Wu Claims Consultant