



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20004972/Utf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 20-04-2020



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2672C	Veh. Inspected	XE 5490A
Policy No.		Coverage (\$)	0.00
Claim No.	M11D10032004	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	06/04/2020

2. Vehicle Particulars & Condition

Make & Model	HINO FS1EKND (M)	c.c	12913
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JHDFS1EKNXXX10050	Colour	ORANGE
Odometer	10227	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm
R/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	6/6/6/6 mm
L/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	6/6/6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/03/2020	Inspection Date	07/04/2020
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**