

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTDG620W507006722

TONG GLEN CLEMENT ALIAS TONG KAH MUN
BLK 175 BISHAN ST 13
#09-155
S 570175

TPS CO
Khanhha

Date :24.04.2020
Vehicle No :SLN 4026 J
Make/Model :TOYOTA WISH
Accident date :30.03.2020

No	DESCRIPTION	Qty	Amount (\$)
----	-------------	-----	-------------

List Items

1	Front bumper <i>Delivered</i>	1	\$ 530.10 ✓
2	Front bumper side holder @ \$188.60 <i>Net new</i>	2	\$ 377.20 124
3	Front bumper reinforcement <i>Net new</i>	1	\$ 318.90 X
4	Front bumper sponge <i>cracked</i>	1	\$ 189.70 ✓
5	Front bumper bracket @ \$189.30 <i>Net new</i>	2	\$ 378.60 X
6	Front bumper lower lip @ \$748.00 <i>Net new</i>	2	\$ 1496.00 X
7	Front bumper fod lamp @ \$408.90	2	\$ 817.80 X
8	Front bumper fod lamp garnish @ \$304.80 <i>{ Net new</i>	2	\$ 609.60 X
9	Front grille <i>lit</i>	1	\$ 408.90 ✓
10	Front headlamp @ \$1883.60 <i>lit</i>	2	\$ 3767.20 2442.
11	Front headlamp lower bracket @ \$189.70 <i>Net new</i>	2	\$ 379.40 X
12	Front bonnet <i>Dented</i>	1	\$ 640.10 ✓
13	Front bonnet hinges @ \$133.50 <i>Net new</i>	2	\$ 267.00 X
14	Front bonnet lock <i>Net new</i>	1	\$ 200.40 X
15	Front bonnet lock bracket <i>Best</i>	1	\$ 191.90 ✓
16	Front bonnet inner rubber <i>Free</i>	1	\$ 208.00 X
17	Front bonnet inner insulation <i>Free</i>	1	\$ 409.00 X
18	Front bonnet centre logo <i>Net new</i>	1	\$ 133.20 58
19	Front support panel <i>Free</i>	1	\$ 1069.50 X
20	Front support top cover <i>Free</i>	1	\$ 318.90 X
21	Front support panel cover clips @ \$14.20 <i>Net new</i>	6	\$ 85.20 X
22	Aircond condenser <i>Delivered</i>	1	\$ 1418.00 ✓
			\$ 14214.60
Less 25% Disc			\$ 3553.65
Total			\$ 10660.95

Special Nett Items

1	Front number plate <i>Best</i>	\$ 50.00 25
2	Front number plate holder <i>Delivered</i>	\$ 50.00 30
Total		\$ 100.00

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TONG GLEN CLEMENT ALIAS TONG KAH MUN

BLK 175 BISHAN ST 13

#09-155

S 570175

Date :24.04.2020

Vehicle No :SLN 4026 J

Make/Model :TOYOTA WISH

Accident date :30.03.2020

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

- 1 Remove & reinstall air con fill in gas
- 2 Remove ,replace & repair consistent to the accident
- 3 Respray painting
- 4 Tuff kote

	\$	150.00	80
1180	\$	1100.00	500
	\$	1000.00	600
	\$	100.00	*
Total	\$	2350.00	

Grand Total \$ 13110.95

total 5844.85

2/5 4.5K

0A Days

4.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: