

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : KAVITA KAN KAN SABNANI NEE SARSATI D/O
28 DUNBAR WALK FRANKEL ESTATE
SINGAPORE 459316

ATTN: FIRST CAPITAL

Your Ref No: TP 0420-5946
Claim Type: Third Party
Accident Date: 02/04/2020
TP Veh Reg No: SHC 3379 C

Estimate No: EST1505925
Date: 02 Apr 2020
Policy No: GA537189
Veh Reg No: SFS9754C
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No: JM6BM42A8F0167095
Engine No: P520255116
Reg. Date: 12/03/2015

Estimate Repair Cost to Vehicle No :SFS9754C

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	1,083.300	1 PC	1,083.30	
2 FRONT BUMPER CLIPS	4.8000	10 PC	48.00	
3 FRONT BUMPER SIDE HOLDER - LH	19.7000	1 PC	19.70	
4 FRONT BUMPER SIDE HOLDER - RH	19.7000	1 PC	19.70	
5 FRONT BUMPER FOG LAMP - LH	369.0000	1 PC	369.00	
6 FRONT BUMPER FOGLAMP COVER - LH	48.8000	1 PCS	48.80	
7 FRONT FENDER - LH	350.6000	1 PC	350.60	
8 FRONT FENDER COWLING - LH	101.9000	1 PC	101.90	
9 FRONT FENDER COWLING CLIPS - LH	4.8000	10 PCS	48.00	
10 HEADLAMP ASSY - LH	2,357.300	1 PCS	2,357.30	
11 HEADLAMP LOWER RETAINER - LH	15.9000	1 PCS	15.90	
			4,462.20	
		Less 20%	892.44	3,569.76
Labour				
12 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	
13 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.0000	1 JOB	600.00	
14 TO CHECK WIRING	50.0000	1 JOB	50.00	
15 TO TUFF-KOTE	30.0000	1 JOB	30.00	
			1,280.00	1,280.00
			Total	S\$ 4,849.76
			Add GST @ 7%	339.48
			Total Amount Payable	S\$ 5,189.24

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED EIGHTY NINE AND CENTS TWENTY FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE