

ASS. REC. BY:

REF:

EQ / 2000 5028/Kp9392

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Auto exel

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1520 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCR 8398UYr Regn: 02, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. 280c.c. 1595Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 18381

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050402R 359831Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / A/Rlm orTyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 8 mmL/Bal. 7 mmL/Bal. 8 mmD.O.A. 6/4/20D.O.I. 7/4/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/4 L1 Rmp @ 4700L Confirmed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Fumes

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

CLOSE: 16/7/2020

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
Resurvey B4pint
4 days
L1Pump & 470dp

Date : 07/04/2020

QUOTATION -THIRD PARTY CLAIM

EQ INSURANCE COMPANY LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 06/04/2020

Claim : Third Party Claim
Veh. No : SCR 8398 U
Model :
Insured Ins: MERCEDES C180
GST Reg. No : 19 - 9603355 - R

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SGM 4194 X		
		REPAIR	
1	BOOTLID	\$ 680.00	2
1	BOOTLID LOCK	\$ 488.50	X
1	BOOTLID WEATHERSTRIP	\$ 120.00	—
1	BOOTLID CENTER LOGO	\$ 98.00	—
1	BOOTLID C 180 EMBLEM	\$ 180.00	—
1	BOOLTID CC EMBLEM	\$ 95.00	—
1	9 G - TRONIC EMBLEM	\$ 2,250.00	LT
2	TAILLAMPS	\$ 780.00	X
2	TAILLAMP LOWER BRACKETS	\$ 558.00	X
1	BOOTLID LOWER LOCK SENSOR	\$ 1,480.00	X
1	END PANEL	\$ 580.00	X
1	END PANEL TOP GARNISH	\$ 1,285.00	—
1	REAR BUMPER	\$ 45.00	—
10	REAR BUMPER CLIPS	\$ 480.00	X
2	REAR BUMPER SIDE RETAINERS	\$ 650.00	2
1	REAR BUMPER REINFORCEMENT	\$ 445.00	X
1	REAR BUMPER SPONGE	\$ 300.00	FS
15	REAR BUMPER RIVETS	\$ 580.00	X
1	REAR BUMPER CENTER BRACKET	\$ 785.60	—
1	REAR BUMPER LOWER GARNISH	\$ 620.00	—
1	REAR BUMPER LOWER CHROME	\$ 550.00	X
1	REAR BUMPER LOWER COVER	\$ 660.00	2HT
2	REAR BUMPER SENSORS	\$ 540.00	2 216
3	REAR BUMPER SENSOR RIM	\$ 560.00	X
1SET	REAR BUMPER SENSOR CABLE	\$ 680.00	X
1	FRONT DRIVER SEAT BELT	\$ 1,850.00	X
1	FRONT DRIVER SEAT BELT ECU		
	TOTAL :	\$ 17,340.10	
	LESS 10%	\$ 15,606.09	
	Total Parts :	\$ 15,606.09	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOEXCEL ENGINEERING PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-15
 Singapore 575722
 Tel: 64535654, 64591639
 Fax: 64591698

	Balance b/f	\$ 15,606.09	
	<u>LABOUR CHARGES</u>		
	Labour charges, to do cutting, welding, replace repair accident affected area	\$ 1,200.00	500
	To remove refix , replace garnish, trim, upholstery etc	\$ 300.00	60
	To do computer setting after repair <i>nn</i>	\$ 300.00	X
	To check wiring system on accident area	\$ 180.00	20
	Anti rust <i>nn</i>	\$ 120.00	X
	To do spray painting on accident affected area	\$ 800.00	500
	To replace rear exhaust <i>nc</i>	\$ 280.00	X
	Total Labour :	\$ 3,180.00	
	TOTAL PARTS & LABOUR :	\$ 18,786.09	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

042I

Vehicle Details

Vehicle No.:

SCR8398U

Vehicle to be Exported:

Yes

Intended Deregistration Date:

07 Apr 2020

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

C180 AVANTGARDE (R17 LED)

Primary Colour:

Grey

Manufacturing Year:

2017

Engine No.:

27491031232078

Chassis No.:

WDD2050402R359631

Maximum Power Output:

115.0 kW (154 bhp)

Open Market Value:

\$37,239.00

Original Registration Date:

09 Feb 2018

First Registration Date:

09 Feb 2018

Transfer Count:

0

Actual ARF Paid:

\$44,135.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

08 Feb 2028

PARF Rebate Amount:

\$33,101.00

Intended COE Rebate Details

COE Expiry Date:

08 Feb 2028

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,289.00

COE Rebate Amount:

\$35,489.00

Total Rebate Amount:

\$68,590.00

The information contained herein is correct as at 07 Apr 2020

OK