

Date: 06.04.2020
 Vehicle No: SGK1177B
 Model: HONDA VEZEL 1.5X HYBRID
 Chassis: RU31204460-2016
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SDU8908X
 Date of Accident: 31.03.2020

Not Attached
Repair B4 pain 4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT FENDER RH	1		<i>B1</i> \$405.20	✓
2	FRONT FENDER 'HYBRID' EMBLEM RH	1		<i>na</i> \$68.50	✓
3	FRONT FENDER INNER LINER CLIPS	8	\$5.50	<i>na</i> \$44.00	✓
4	FRONT FENDER EXTENSION COVER RH	1		<i>na</i> \$172.10	✓
5	FRONT BUMPER SIDE BRACKET RH	1		<i>na</i> \$29.50	X
6	FRONT DOOR RH	1		<i>na</i> \$936.40	X
7	FRONT BUMPER CLIPS	8	\$5.50	<i>na</i> \$44.00	✓
8	FRONT BUMPER	1		REPAIR	
SUB TOTAL				\$1,699.70	733.80
LESS 20%				-\$339.94	146.76
PARTS TOTAL				\$1,359.76	\$ 587.04

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC. *400* \$480.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH. *na* \$120.00 X

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC. *na* \$60.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH & FRONT DOOR RH. *680* \$750.00

LABOUR TOTAL \$1,410.00

TingAn

TOTAL \$2,769.76

Finalize: Paint: \$ 587.04
Labour: \$ 1080.00
\$ 1667.04 *7/7/2020*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____