

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/04/2020 15:40

JOB-NO: 50112564

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7534U

TRANS: AUTO

CHASSIS: JTDKB3FU103078297

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2B89435

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	1,400.00	0.00	1,400.00	-	800	Y
2 RUST PROOFING	1.00	180.00	0.00	180.00	30		Y
3 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200		Y
4 RESPRAY REAR BUMPER DIFFUSER	1.00	250.00	0.00	250.00	X		Y
5 RESPRAY REAR BUMPER DIFFUSER EXT COVER	1.00	250.00	0.00	250.00	80		Y
6 RESPRAY REAR BOOT LID REGISTERED GARNISH	1.00	250.00	0.00	250.00	150		Y
7 RESPRAY REAR BOOT LID	1.00	250.00	0.00	250.00	200		Y
8 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	200		Y
9 R&R REVERSE SENSOR, CHECK WIRING	1.00	120.00	0.00	120.00	30		Y
10 R&R TAIL LAMP AND REPOSITION	1.00	80.00	0.00	80.00	X		Y
11 R&R REAR BOOT LID WINDSCREEN BOTTOM	1.00	100.00	0.00	100.00	X		Y
TOTAL:		3,380.00	0.00	3,380.00			

MATERIALS

1 REAR BUMPER / 00	1.00	490.50	122.63	367.87	L	Y	
2 REAR BUMPER REINFORCEMENT	1.00	318.80	79.70	239.10	L	Y	
3 REAR BUMPER RETAINER RHS / JA	1.00	92.30	23.08	69.22	L	Y	
4 REAR BUMPER RETAINER LHS / BR	1.00	92.30	23.08	69.22	L	Y	
5 REAR BUMPER DIFFUSER / 00	1.00	558.30	139.58	418.72	L	Y	
6 REAR BUMPER TOWING CAP / M1J	1.00	35.60	8.90	26.70	L	Y	
7 REAR BUMPER DIFFUSER EXTENSION RHS X	1.00	119.90	29.98	89.92	L	Y	
8 REAR BUMPER DIFFUSER EXTENSION LHS X JA	1.00	119.90	29.98	89.92	L	Y	
9 REAR END PANEL	1.00	629.80	157.45	472.35	L	Y	
10 REAR END PANEL TOP GARNISH	1.00	122.80	30.70	92.10	L	Y	
11 REAR BUMPER LOWER COVER RHS X	1.00	154.60	38.65	115.95	L	Y	
12 REAR BUMPER LOWER COVER LHS X	1.00	154.60	38.65	115.95	L	Y	
13 REAR BOOT LID (REPAIR) X R	1.00	0.00	0.00	0.00	L	Y	
14 REAR BOOT EMBLEM-LOGO / APC	1.00	56.70	14.18	42.52	L	Y	
15 REAR BOOT LID EMBLEM-PRIUS / MC	1.00	59.95	14.99	44.96	L	Y	
16 REAR BOOT LID EMBLEM-HYBRID / MC	1.00	49.97	12.49	37.48	L	Y	
17 REAR BOOT LID REGISTERED GARNISH / BR	1.00	891.20	222.80	668.40	L	Y	
18 REAR BOOT LID LOCK / M1J	1.00	452.21	113.05	339.16	L	Y	
19 REAR BUMPER CLIP SET / MC	1.00	45.00	0.00	45.00	30 S	Y	
20 REAR BUMPER REVERSE SENSOR SET / BR	1.00	240.00	0.00	240.00	200 S	Y	

G-STAR-WI-ET-001-02-Rev00

* REAR BUMPER UNDERCARRIAGE 1.00 / BR
COVER

* REAR BUMPER UNDERCARRIAGE
COVER CLIPS SET / MC

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
21 REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	
22 REAR BOOT LID STICKER-COMFORT DELGO BOOKING 65521111	1.00	150.00	0.00	150.00	S	Y	
23 REAR BOOT LID STICKER-APPS BOOK NOW	1.00	150.00	0.00	150.00	S	Y	
24 REAR BOOT LID BOTTOM SEALANT	1.00	150.00	0.00	150.00	S	Y	
25 REAR BUMPER PROTECTOR PAD	1.00	120.00	0.00	120.00	S	Y	
TOTAL:		5,334.43	1,099.89	4,234.54			
TOTAL PARTS & LABOUR:		8,714.43	1,099.89	7,614.54			

EXCESS/LOADING:S\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY:

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: