



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002788
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 28/04/2020
Reference NS/INC20005102/Fvf3n2
Code INC4



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 8649R
Insured Veh. SCG 2232L
Claim No. 1091814-001
Policy No. 5101282432-01
Accident Date 07/04/2020
Inspection Date 08/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

HYN




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005102/Fvf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 28-04-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCG 2232L	Veh. Inspected	SHC 8649R	
Policy No.	5101282432-01	Coverage (\$)	0.00	
Claim No.	1091814-001	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU083000	Colour	BLUE	
Odometer	504407	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	8 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	8 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	07/04/2020	Inspection Date	08/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8649R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40VC PANEL ASSY-FR DR LH	DENTED	2,256.40	2,256.40
1	I40VC PANEL ASSY-RR DR LH	DENTED	2,201.10	2,201.10
1	I40VC MOULDING ASSY-SIDE	NOT NECESSARY	341.40	-
	LESS 20% DISCOUNT		-959.78	-891.50
			3,839.12	3,566.00
<u>NETT ITEMS</u>				
1	(I40) FRT DOOR LOGO SONATA (N)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CC (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	FRT DOOR ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	ROCKER PANEL ADVERTISEMENT LOGO LH (SN)	NECESSARY	50.00	50.00
			350.00	350.00
<u>LABOUR</u>				
	PANEL BEATING.(REPAIR FRT FENDER LH).		700.00	560.00
	SPRAYPAINT ON AFFECTED AREA.		800.00	550.00
	TUFF COAT ON AFFECTED PARTS.		50.00	50.00
	TRANSFER OF FRT DOOR LH.		120.00	90.00
	TRANSFER OF REAR DOOR LH.		120.00	90.00
	-		-	-
	-		-	-
	-		-	-
			1,790.00	1,340.00
GRAND TOTAL			6,118.62	5,395.50

Report Ref No. NS/INC20005102/Fvf3n2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,300.00
---	--	--	-----------------

Report Ref No. NS/INC20005102/Fvf3n2



PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.