



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIU'S BROTHER AUTO WORKSHOP BLK 1 KAKI BUKT AVE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883 ON BEHALF OF GOLDBELL LEASING PTE LTD			Ref: CC6/TP20005105/Uga3q2 Date: 07/04/2021 Code: TP105	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	GBF 238B	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	09/04/2020	
2. Vehicle Particulars & Condition				
	Make & Model	FIAT DOBLO CARGO (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ZFA26300006C06696	Colour	WHITE
	Odometer	92644 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	FALKEN	6 mm
	L/H Front Tyre	195/50 R16	FALKEN	6 mm
	R/H Rear Tyre	195/50 R16	FALKEN	6 mm
	L/H Rear Tyre	195/50 R16	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/04/2020	Inspection Date	09/04/2020
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	