

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305392689

Date : 13/04/20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6548 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHC8616K

Date of Accident : 07-Apr-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SFT2320L

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

\$750.00


**\$750.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : RAM

Date : 16/04/2020

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

## COMFORTDELGRO PTE LTD

## REPAIR ESTIMATE

Vehicle No.: SHC8616K

Make: TOYOTA

Model: PRIUS

DOA:

Date: 4/7/2020

Insurance: CHINA

MVA: LIM TS

Qty	Parts Description / Labour	Qty	Unit Price	Amount
1	REAR BUMPER DEF/CVA			\$458.60
1	REAR BUMPER SIDE RETAINER RH Xnn			\$112.70
1	TOWING COVER Xnn			\$82.70
	<b>SUB TOTAL</b>			\$654.00
	<b>LESS 25%</b>			\$163.50
				\$490.50
1	REVERSE SENSOR Xnn			135.70
				135.70
	<b>Labour Charge</b>			
	PANEL BEATING			380.00 \$320
	SPRAY PAINTING			400.00 \$200
	WIRING			60.00 <del>\$60</del> Xnn
	TUFF KOTE			60.00 \$30
	REMOVE/REFIX REVERSE SENSOR			60.00 /
	<b>TOTAL LABOUR</b>			\$960.00
	<b>ESTIMATE TOTAL</b>			\$1,586.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Part.: 343.95  
 Lab.: 610.00  
 T: 953.95  
 Less 20% 190.79  
 4S \$ 750.00

Ran (LKK)  
 8/04/2020 1230  
 Paregura@lkkauto.com  
 88622778  
 2ft repair photo  
 2 repair days