



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHIAM STELLA (ZHAN HUIQI)	Cust No/Name	/CHIAM STELLA (ZHAN HUIQI)
5 BUKIT BATOK STREET 25	Reg No/Reg Date	SMK3324J / 05/04/201
#13-11	Date In/Mileage	/ 0
SINGAPORE 658880	Chassis No	KNAF3416MK5031203
Contact No Mobile: 91726076	Engine No	G4FGJH722209
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00081	Cash	07/04/2020/ 15:51	QUE	261 / Edwin Caina	14545	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000						1100 2750.00
RENEW RR BUMPER						
REPAIR RR END PNL , BOOTLID & RHR FENDER						
E PNT98000						840 2100.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID , RHR FENDER & RR FLR PNL						
E PNT88000						275.00
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR						
A 54900099						30 50.00
CHECK WIRING ELECTRICAL SYSTEM						
A 10028901						200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN-PRO TEST						
USING HI-SCAN PRO TEST						
M SUNDRY						120.00
APPLY ANTI CORROSION ON AFFECTED AREAS						
E PNT88000						80 100.00
REMOVE & REFIT REVERSE SENSOR						
M SUNDRY						220.00
SUPPLY REVERSE SENSOR						
M SUNDRY						40.00
SUPPLY C&C BADGE						
M SUNDRY						20 50.00
Sundries						
M COVER-RR BUMPER			1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR			1.00	241.00	00.00	241.00
M COVER-RR BUMPER UNDER,LH			1.00	33.00	00.00	33.00
M COVER-RR BUMPER FOG LAMP,RH			1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL,RH			1.00	181.00	00.00	181.00
M EXTN WIRING ASSY-BWS			1.00	207.00	00.00	207.00
M BEAM-RR BUMPER			1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH			1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH			1.00	65.00	00.00	65.00
M ANTENNA ASSY-SMARTKEY			1.00	46.00	00.00	46.00
M BRACKET-RR BEAM UPR MTG,LH			1.00	9.00	00.00	9.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
CHIAM STELLA (ZHAN HUIQI) 5 BUKIT BATOK STREET 25 #13-11 SINGAPORE 658880 Contact No Mobile: 91726076	Cust No/Name	/CHIAM STELLA (ZHAN HUIQI)
	Reg No/Reg Date	SMK3324J / 05/04/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031203
	Engine No	G4FGJH722209
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/04/2020/ 15:51	QUE	261 / Edwin Caina	14545			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM UPR MTG, RH <i>7.00</i>				1.00	9.00	00.00	9.00
M	BRACKET-RR BEAM LWR, CTR <i>7.00</i>				1.00	6.00	00.00	6.00
M	BRACKET-RR BEAM LWR MTG <i>7.00</i>				1.00	6.00	00.00	6.00
M	COVER-RR BUMPER UNDER, RH <i>7.00</i>				1.00	33.00	00.00	33.00
M	BRACKET ASSY-RR BPR SIDE UPR, L <i>7.00</i>				1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR, R <i>7.00</i>				1.00	31.00	00.00	31.00
M	LOGO ASSY-KIA SUB <i>X</i>				1.00	32.00	00.00	32.00
M	EMBLEM-CERATO <i>X</i>				1.00	28.00	00.00	28.00

Estimate

SURVEYOR NAME: Ram - Hg 90010068SURVEYOR SIGNATURE: [Signature]DATE: 08/06/2020 @ 1030REMARKS: 4 daysResurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	7,910.00
7% GST on	7910.00	553.70
Total Payable		8,463.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : FIRST CAPITAL

Supplementary For Registration No.: SMK 3324 J

<u>Labour</u>		<u>Cost (\$)</u>
1	Towing from Bt. Batok St. 25 to C&C Pandan Gardens	110.00 ✓
	7% GST	7.70
	Total	117.70

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

24
HOURS

HOTLINE: 9182 8211

ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1234250

Date: 27/04/2020

M/S:

Cycle & Carriage KIA NIP# 14545

Vehicle No: 9mk 3324J. Model : Kia Cevato

From: 5 Bl. Batok St 25 Time Start: 0850

To: 209 Pandan Gardens Time End:

Remarks: Stella chiam 91726076

☐ Change Tyres / Jump Start☒ Accident☐ Use Car Carrier☒ Basement / Multi Carpark☐ Crane Up / Winch Out☐ Open Door☐ Using King Dolly☐ Dismantle Shaft / Brake☐ Loaded

AMOUNT S\$

GST S\$

TOTAL S\$

Received By

**bizSAFE₃**

Important Note:

Kun Selg
Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.