

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD Ref : CS/UOI20005127/R1yf3e2					
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date: 13-05-2020 Code: UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBK 2547U	Veh. Inspected	SLA 534D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M11D10142004	Excess (\$)	0.00	
	Assign From	KATIE LEE	Assign Date	08/04/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI ELANTRA 1.6 AT	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KMHDH41CMGU656535	Colour	WHITE	
	Odometer	113564	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/04/2020	Inspection Date	09/04/2020	
	Survey held at	48 TOH GUAN ROAD EAST #05-123			
	Repairer	Repairer VAG SINGAPORE PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				