

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201500371E

Date: 09/04/20

By Fax &/ Email

To: AIG

Attn : Motor Claims Department

Re: Accident involving motor vehicle Nos. SMF9776A and SJG9601B
along Cross Junction of Punggol Way and TPE (At Punggol
West Flyover) on 02/04/20.

We refer to the above matter.

We are instructed by Vincar Leasing And Rental Pte. Ltd. to notify you of a road traffic accident
on 02/04/20 at about 13:30 at Cross Junction of Punggol Way and TPE (At Punggol
West Flyover) involving our client's/customer's vehicle registration number SMF9776A and vehicle
registration number SJG9601B (your insured) at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our
client/we proceed to repair the damaged vehicle, please let us know within 2 working days of
your receipt of this notice whether you or your insurer would like to conduct a pre-repair
survey of the vehicle. If we do not receive any reply from you within the stipulated timeline,
our client/we shall proceed to repair the vehicle without further reference to you.

Thank You.

Yours faithfully



Abby

Hp : 9856 4815