

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 24-Mar-18

Address : SMOOTH DR
BLK 681A JURONG WEST CENTRAL 1
14-96
SINGAPORE 641681

Reference : TP 1152/03/18
Vehicle No : SGV4205B
Make/Model : TOYOTA AXIO
Insurance Co. : NTUC

RE : QUOTATION REPAIRS TO SGV 4205B FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY	AMT \$	
1)	REAR BUMPER	1	\$ 1,051.20	DE -
2)	REAR BUMPER RETAINER	2	\$ 91.20	NE -
3)	REAR BUMPER BRACKET	2	\$ 97.20	NE -
4)	REAR BUMPER REVERSE SENSOR	1	\$ 288.01	NE S/N 200 - S/N
5)	TAIL LAMP	2	\$ 437.81	LH-CRA/RH-?X NE
6)	BOOT COVER	1	\$ 539.67	BT -
7)	BOOT COVER WEATHERSTRIPE	1	\$ 185.65	NE -
8)	END PANEL	1	\$ 394.60	PA - 4521.09
9)	END PANEL GARNISH	1	\$ 128.70	DE - 25%
10)	SPARE TYRE COVER	1	\$ 168.67	CUT -
11)	"AXIO" EMBLEM	1	\$ 48.60	NE - 3390.81
12)	"TOYOTA" LOGO	1	\$ 47.20	NE -
13)	"X" LOGO	1	\$ 39.60	NE -
14)	FRONT BUMPER	1	\$ 1,154.20	DE -
15)	FRONT BUMPER GRILLE	1	\$ 285.70	CRA -
16)	BUMPER CLIPS	20	\$ 70.00	NE -
LIST PRICE TOTAL			\$ 5,028.01	
LESS DISCOUNT 25%			\$ 1,257.00	
LIST PRICE TOTAL AFTER LESS			\$ 3,771.01	

17) FRT NOS PLAE WITH CASING

\$ 58.00 35 PA S/N

NETT PRICE TOTAL

\$55.00 200 - S/N

TOTAL PARTS COST

\$3,826.01

= 235

LABOUR AND MISCELLANEOUS CHARGES

- 1) TO REMOVE & REPLACE FRONT BUMPER & REAR COVER, REAR BUMPER AND TO PANEL BEAT CUT & WELD END PANEL INCLUDING FRT BONNET AND PANEL. \$ 1,600.00 ¹³⁰⁰ ~~1200~~ (8 DAYS)
- 2) TO PUTTY AND SPRAY PAINT TO FRT AND REAR BOOT COVER, END PANEL, TYRE PANEL, BOTH REAR FENDERS, BONNET, FRT SUPPORT PANEL AND BOTH FENDERS. \$ 2,400.00 ¹⁴⁰⁰ ~~1000~~ (12 PANEL)
- 3) TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP \$ 120.00 ³⁰ ~~90~~
- 4) TUFF KOTE \$ 300.00 ¹⁵⁰ ~~150~~

LABOUR TOTAL

\$ 4,420.00

TOTAL ESTIMATED REPAIR COST

\$ 8,246.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resme

Hp 90010068

12 days

4/8

28/03/18 @ 1740

Resy after repair

3390.81

235.00

2880.00

6505.81

20%

5204.64

12 days

45-5,200