



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE20005200/Uyf3e2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 29-06-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 916Y	Veh. Inspected	GBH 6714T
Policy No.		Coverage (\$)	0.00
Claim No.	VC013661	Excess (\$)	0.00
Assign From	JENNY TOH	Assign Date	14/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFAT35Y50K211203	Colour	SILVER
Odometer	57499	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	5 mm
L/H Front Tyre	195 R15	YOKOHAMA	5 mm
R/H Rear Tyre	155 R12 (D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	155 R12 (D)	YOKOHAMA	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2020	Inspection Date	16/04/2020
Survey held at	KAIZEN MOTORS (ENGINEERING) PTE LTD 68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------