## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

Chan, Yoke Shi

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 28 May 2020

# **Preliminary Advice**

Vehicle No : SMM4965S Accident Date : 08/04/2020 Make : AUDI A4 Policy No. : 1900114746 **Assignment Date** : 14/04/2020 **Excess** : S\$800.00 Date of Inspection : 14/04/2020 Est. Duration of Repair : 10 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,164.00 (inclusive supp)
Revised Amount	:S\$	35,573.00 (inclusive supp)
Check Items (Estimated)	:S\$	1,670.00
Total	:S\$	37,243.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 128,000.00

 COE / PARF Rebate
 :S\$ 73,575.00

Salvage Value :S\$

Margin for Repair :S\$ 54,425.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	
	Kindly let us have your authorisation.	

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(  $\,$  X  $\,$  ) Other comments : Supplementary amount is \$ 2,201.00