

Car City Auto Centre Pte Ltd
#01-198, Blk 9006 Tampines Street
93,
528840

Insurer Reference:
Repairer Reference: TP/20014
Date calculated: 28/04/2020 11:38 AM

Full Report
Registration: SLD6789E
Printed: 28/04/2020 11:38 AM

Summary Information

Claim

| | | | |
|------------------------|----------------|-------------------|---|
| Location: | Singapore (SG) | Work Provider: | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by: | HO TOO BOON | Currency: | SGD |
| Claim Reference: | | Date of Incident: | 07/04/20 |
| Estimated Repair Time: | | Hire Car Start: | |
| Actual Repair Days: | | Hire Car End: | |

Vehicle Details

Vehicle

| | |
|---------------------|-------------------|
| Manufacturer: | MITSUBISHI |
| Model: | OUTLANDER(GF-GG) |
| Sub Model: | BASE MODEL |
| Model Sheet Number: | 32 70 01 |
| Registration: | SLD6789E |
| VIN number: | JMYXTGF3WGZ001388 |
| Odometer: | 9999 |

Model Specs

| | | | |
|-------------------|---------------------|---------------|----------------------|
| FROM 05/2013 | WING MOULDING | STEEL BUMPER | TAILGATE MLDG CHROME |
| ELECTRIC TAILGATE | REAR PARKING SYSTEM | REAR MUDFLAPS | |


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

| Code | Description | Time Base 10 WU/h | Price = 42.00 SGD/h | |
|----------------------------------|--|-------------------|---------------------|---------------|
| | | | WU | Price SGD |
| NO NUMBER | PREPARATION TIME | | 2.0 | 8.40 |
| 514210 00) | R + R REAR BUMPER | | 2.0 | 8.40 |
| NO NUMBER | REAR BUMPER (REMOVED) RENEW INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT | | 4.0 | 16.80 |
| NO NUMBER | R + R REAR PARKING AID SENSORS ADD/WORK | | 2.0 | 8.40 |
| NO NUMBER | R + R REAR BUMPER REINFORCEMENT | | 2.0 | 8.40 |
| NO NUMBER | RENEW BOOTLID LOCK CATCH | | 3.0 | 12.60 |
| 424310 00 | R + R TAILGATE | | 9.0 | 37.80 |
| 424311 00ZAX | RENEW TAILGATE (TAILGATE REMOVED) INCLUDES: R + R REAR SCREEN AND ALL ATTACHED PARTS, ALIGN + ADJUST | | 26.0 | 109.20 |
| 541310 00 | R + R LEFT TAIL LAMP | | 3.0 | 12.60 |
| 541310 00 | R + R RIGHT TAIL LAMP | | 3.0 | 12.60 |
| 2650 | REAR BUMPER MNTG KIT CHECK | | | |
| Labour Cost | | Hrs | WU | |
| Panel / Mechanical Labour | | 5.60 | 56.0 | 235.20 |
| Total of Labour | | | | 235.20 |

Paint

| Paint Work | | SYSTEM AZT | Time Basis 10 WU/h | |
|------------|--|------------|--------------------|-----------|
| Code | Description | | WU | Price SGD |
| | BOOTLID/TAILGATE NEW PART PAINTING | | 18.0 | |
| | REAR COVER BUMPER NEW PART PAINT K1G/P | | 20.0 | |
| | RR LWR BUMPER COVER NEW PART PAINT K1G/P | | 10.0 | |
| | R/R OUT BUMPER TRIM NEW PART PAINT K1G/P | | 4.0 | |
| | L/R OUTER SENSOR SURFACE PAINT PLAST. | | 3.0 | |
| | R/R OUTER SENSOR SURFACE PAINT PLAST. | | 3.0 | |
| | L/R OUT QTR PANEL SURFACE PAINT | | 7.0 | |
| | R/R OUT QTR PANEL SURFACE PAINT | | 7.0 | |

Paint Material Per Part

| Code | Description | Price SGD |
|------|--|-----------|
| 2931 | BOOTLID/TAILGATE NEW PART PAINTING | 44.73 |
| 2583 | REAR COVER BUMPER NEW PART PAINT K1G/P | 66.70 |
| 2590 | RR LWR BUMPER COVER NEW PART PAINT K1G/P | 27.29 |
| 3420 | R/R OUT BUMPER TRIM NEW PART PAINT K1G/P | 3.79 |
| 2679 | L/R OUTER SENSOR SURFACE PAINT PLAST. | 0.26 |
| 2680 | R/R OUTER SENSOR SURFACE PAINT PLAST. | 0.26 |
| 3481 | L/R OUT QTR PANEL SURFACE PAINT | 12.50 |
| 3482 | R/R OUT QTR PANEL SURFACE PAINT | 12.50 |

| Labour Cost - Paint | | Hrs | WU | Price SGD |
|--------------------------------|----------------|-------------|-------------|---------------|
| Factor | 42.00 SGD/h | | | |
| Time Paint | | | 72.0 | |
| Preparation Main Work Metal | | 0.60 | 6.0 | 25.20 |
| Preparation Comp. Work Plastic | | 1.00 | 10.0 | 42.00 |
| Total | 10 WU/h | 8.80 | 88.0 | 369.60 |

| Material Cost - Paint | Price SGD |
|-------------------------------------|---------------|
| New Part Painting | 44.73 |
| New Part Painting - Plastic K1G/PUR | 97.78 |
| Surface-/Blend Paint | 25.00 |
| Surface Painting Plastic | 0.52 |
| Material-constant Metal | 12.70 |
| Material-constant Plastic | 16.20 |
| Total | 196.93 |

Spare Parts

prices as at 2015-06-01
Price SGD

| Code | Description | Part Number | | Price SGD |
|------|----------------------|------------------|----------|-----------|
| 3021 | BADGE MODEL | 7415A401 | Original | 50.00 |
| 3023 | BADGE MODEL | 7415A341 | Original | 35.00 |
| 2987 | BOOT/T-GATE MOULDING | 5817A292HB | Original | 265.00 |
| 2931 | BOOTLID/TAILGATE | 5801B348 | Original | 700.00 |
| 4915 | L/TAILGATE SEAL | 5805A315 | Original | 25.00 |
| 4917 | LOWER TAILGATE SEAL | 5805A317 | Original | 25.00 |
| 4916 | R/TAILGATE SEAL | 5805A315 | Original | 25.00 |
| 2656 | REAR BUMPER CLIP | MU488006 | | 0.00 |
| 2650 | REAR BUMPER MNTG KIT | USE SINGLE PARTS | | |
| 2583 | REAR COVER BUMPER | 6410C887 | Original | 500.00 |
| 3020 | REAR MANUFACT BADGE | 7415A479 | Original | 35.00 |
| 3160 | REAR SCREEN BOND KIT | KNGKWI2 | | 0.00 |
| 3163 | REAR SCREEN FIX SET | USE SINGLE PARTS | | |
| 1417 | REAR SPACER | MR462285 | | 0.00 |
| 1005 | REAR TAILGATE LAMP L | TAILGATE LAMP | Original | 225.00 |
| 1004 | REAR TAILGATE LAMP R | TAILGATE LAMP | Original | 225.00 |
| 2653 | SCREW | MS100222 | | 0.00 |
| 2654 | SCREW | MU440019 | | 0.00 |
| 2657 | SCREW | MF453047 | | 0.00 |
| 2658 | SCREW | MF911345 | | 0.00 |
| 4918 | TAILGATE UPPER SEAL | 5805A316 | Original | 25.00 |

| | | |
|------------------|-----------------|----------|
| f: OEM Parts | Savings | 0.00 |
| n: Non-OEM Parts | Subtotal | 2,135.00 |
| u: Used parts | Total | 2,135.00 |

Extras

| Code | Description | Price SGD |
|------|---------------------------|--------------|
| 1000 | BUMPER CLIPS SUNDRY PARTS | 20.00* |
| 1003 | C & C LOGO EMBLEM | 20.00* |
| 1006 | SEALANT SEALANT | 25.00* |
| | Total Extras | 65.00 |

| Code | Description | Price SGD |
|------|-------------|-----------|
|------|-------------|-----------|

Final Calculation

| | SGD | SGD |
|---------------------------------------|----------|-----------------|
| Parts | 2,135.00 | |
| Total Parts | | 2,135.00 |
| Labour Time Base 10 WU/h | | |
| Total 56.0 WU X 42.00 SGD/h | 235.20 | |
| Total of Labour | | 235.20 |
| Total Of Extras | | 65.00 |
| Paint Work Time Base 10 WU/h | | |
| Labour Cost 88.0 WU X 42.00 SGD/h | 369.60 | |
| Material Cost | 196.93 | |
| Total Paint Including Material | | 566.53 |
| Repair Cost Excludes GST | | 3,001.73 |
| GST (+7.0%) | | 210.12 |
| Repair Cost Included GST | | 3,211.85 |

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 0930



Dept Direct: 6305 0910

Dept Direct: 6305 0911

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made In Korea),
Forch (Made In Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

CAR CITY AUTO CENTRE PTE LTD
BLK 9006 TAMPINES ST 93
#01-198

SINGAPORE 528840
TEL : 67810300 FAX : 67820300
ATTN : HO 96214666

TAX INVOICE : AR202004-05542
DATE : 20/04/2020
CUSTOMER ID : CAR018
VEH REG. NO. : SLD6789E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR. : S\$

| SQ STOCKID | DESCRIPTION | StkLoc | QTY | U/PRICE | AMOUNT |
|---|------------------------------------|---------|-----|---------|--------|
| 8. JJ7415A479 GK1W GF3W | MARK MITSUBISHI | WH 2H18 | 1 | 45.00 | 45.00 |
| 9. JJ5817A265WA/WC GF3W | ✓ GARNISH, TAILGATE | WH 2C10 | 1 | 265.00 | 265.00 |
| 10. JJMZ380423EX ALL | ✓ DECAL, MIVEC | WH 2D10 | 1 | 35.00 | 35.00 |
| 11. MLD.MIT OUTLAN 15"RR TOP GF3W OUTLANDER 15" | 3805A316 RR GLASS MLD TOP 1BOX3 | WH | 4 | 25.00 | 100.00 |

2135.00

SUB-TOTAL : 2,530.00
ADD GST 7.00 % 177.10

E. & O.E

TOTAL AMOUNT S\$: 2,707.10

[E] 20/04/2020 2:49:33PM

[P] 24/04/2020 12:55:48PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN



* A R 2 0 2 0 0 4 - 0 5 5 4 2 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9030



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CAR CITY AUTO CENTRE PTE LTD

BLK 9006 TAMPINES ST 93

#01-198

SINGAPORE 528840

TEL : 67810300 FAX : 67820300

ATTN : HO 96214666

TAX INVOICE : AR202004-05542

DATE : 20/04/2020

CUSTOMER ID : CAR018

VEH REG. NO. : SLD6789E

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR. : S\$

| SQ | STOCKID | DESCRIPTION | StkLoc | QTY | U/PRICE | AMOUNT |
|----|----------------------------------|--------------------------------------|------------|-----|---------|--------|
| 1. | JJ5801B351 GF3W 15 | ✓ PANEL ASSY, TAILGATE 2931 | WH UI | 1 | 700.00 | 700.00 |
| 2. | JJ6410F374/6410D243 GF3W 2019 | ✓ FACE, RR BUMPER 2583 | WH 3A2 | 1 | 500.00 | 500.00 |
| 3. | JJ8330B174 GF3W 15" | Return TAIL LAMP ASSY RH(LED) return | WH 2R32 | 1 | 350.00 | 350.00 |
| 4. | JJ8331A179 GF3W 15" | ✓ LAMP ASSY, TAIL BOOT, LH(LED) 1005 | WH 2D5 | 1 | 225.00 | 225.00 |
| 5. | JJ8331A180 GF3W 15" | ✓ LAMP ASSY, TAIL BOOT, RH(LED) 1004 | WH 2D5 | 1 | 225.00 | 225.00 |
| 6. | JJ7415A015 HA1W, CW5 NA4W, | ✓ MARK, THREE-DIA 3020 | WH II13 | 1 | 35.00 | 35.00 |
| 7. | JJ7415A401 GF3W | ✓ MARK, OUTLANDER 3021 | WH II26 | 1 | 50.00 | 50.00 |

2131

CONTINUE NEXT PAGE

[P] 24/04/2020 12:55:48PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 20/04/2020 2:49:33PM