



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD19019550/Eyf3e2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 29-04-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGM 6613R	Veh. Inspected	SKE 6317R
Policy No.	PNCV2019-00000819	Coverage (\$)	0.00
Claim No.	1201900033835	Excess (\$)	0.00
Assign From	CLARA LI ZI RONG	Assign Date	14/04/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	GE61210199	Colour	BLACK
Odometer	159138	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R14	YOKOHAMA	5 mm
L/H Front Tyre	185/65 R14	YOKOHAMA	5 mm
R/H Rear Tyre	185/65 R14	YOKOHAMA	5 mm
L/H Rear Tyre	185/65 R14	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2019	Inspection Date	05/11/2019
Survey held at	MAJESTY AUTOWERKS-39 WOODLAND CLOSE #01-36		
Repairer	-		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------