

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car

Reg. No. : PC 4293 P

Make / Model : MITSUBISHI

Chassis No : _____

Name of Driver : HO KAH KIT

Date/Time of Accident : 26/03/2020 16:15

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / AIS / Others _____ MSIG : _____

Vehicle is Towed Back ? YES / NO Date / Time : _____

Accident reporting date : 30/03/2020 11:00

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any : _____

TP INSURANCE LUMP SUM REPAIR


Ref. No. BPS/03/20/3002

Reg. Date : _____

Mileage : _____

Rental/Replacement Vehicle : Yes / No

The damages on the vehicle are as indicated in the following diagram :



Signed : _____ Date : _____

Accident Repair Job Card No	:	_____	Date Prepared	:	_____
Summary of Repair Estimates			Repair Completed	:	_____
		Quotation from ARC			Adjusted by Surveyor, if applicable
Total Labour Charges	:	\$ 500.00			\$ -
Total Spray Painting Charges	:	\$ 550.00			\$ -
Total Material Charges	:	\$ 1,575.88			#REF!
Other Charges	:	\$ 210.00			#REF!
TOTAL	:	\$ 2,835.88			\$ -
			Lump Sum Repair, if any	:	_____
No. of Repair Days	:	[] days			[] days
Signature	:	Prepared by: _____			Adjusted by: _____

QN No. _____ Invoice No. _____

Signed : _____ Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	
TO RENEW REAR DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 500.00	300
Total Labour Cost	\$ 500.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
TO RESPRAY AFFECTED AREAS	\$ 550.00	400
Spray Painting	\$ 550.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
TO TUFFCOAT AFFECTED AREA	\$ 150.00	30
TO REMOVE / REFIX WIRING CHECKS	\$ 60.00	20
Total Other Costs	\$ 210.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	List Price (\$)	Discount 25%	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
1	REAR BUMPER	1	\$ 1,588.97	25%	\$ 1,191.73	X R	
2	REAR BUMPER SIDE BRACKET RH	1	\$ 113.60	25%	\$ 85.20	X R	
3	REAR BUMPER REFLECTOR RH	1	\$ 212.65	25%	\$ 159.49	X R	
4	REAR BODY PANEL SIGNAL LAMP RH	1	\$ 185.95	25%	\$ 139.46	/ CRU	
TOTAL MATERIALS			\$ 2,101.17		\$ 1,575.88		

Surveyor Remark:

Repair day - 2 days
L/S
After paint photo
SunPn (LKR)

16/04/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: