



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE CIVIL DEFENCE FORCE

Ref : CS/SCD20005263/Qqf3e2

91 UBI AVE 4 SINGAPORE 408827

Date : 24-04-2020



ATTN : SHAUN LIM CHI TUCK

Code : SCD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 1546H
Policy No.		Coverage (\$)	0.00
Claim No.	ACC-IND-20-04	Excess (\$)	0.00
Assign From	SHAUN LIM CHI TUCK	Assign Date	16/04/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WDB9066332P637686	Colour	WHITE
Odometer	19604	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R16	GOODYEAR	6 mm
L/H Front Tyre	225/65 R16	GOODYEAR	6 mm
R/H Rear Tyre	225/65 R16	GOODYEAR	6 mm
L/H Rear Tyre	225/65 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/03/2020	Inspection Date	17/04/2020
Survey held at	K & S BODYWERKZ-NO2 2B SUNGEI KADUT DRIVE		
Repairer	-		

5a. Remarks

--