



Registration No. QX 1546H

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Wind screen	1			\$0.00	
1.2	Wind screen moulding	1			\$0.00	
1.3	Wind screen wiper sensor	1			\$0.00	
1.4	Wind screen sealant	1			\$0.00	
1.5	Wind screen primer	1			\$0.00	
1.6	Bonnet	1			\$0.00	
1.7	Bonnet upper lock	1			\$0.00	
1.8	Bonnet lower lock	1			\$0.00	
1.9	Bonnet insulator	1			\$0.00	
1.10	Bonnet hinge RH/LH	2			\$0.00	
1.11	Bonnet stand	1			\$0.00	
1.12	Bonnet garnish	1			\$0.00	
1.13	R/H dented fender	1			\$0.00	
1.14	R/H fender inner panel	1			\$0.00	
1.15	R/H head lamp	1			\$0.00	
1.16	R/H head lamp wiper nozzle	1			\$0.00	
1.17	Front bumper	1			\$0.00	
1.18	Front bumper retainer RH/ LH	2			\$0.00	
1.19	Front bumper support	1			\$0.00	
1.20	Front bumper sensor	1			\$0.00	
1.21	R/H fog lamp	1			\$0.00	
1.22	Front number plate	1			\$0.00	
1.23	Siren speaker	2			\$0.00	
1.24	Siren rumble	1			\$0.00	
1.25	AP Panel	1			\$0.00	

1.26	Radiator grill	1			\$0.00	
1.27	Head lamp support	1			\$0.00	
1.28	Radiator	1			\$0.00	
1.29	Radiator upper hose	1			\$0.00	
1.30	Radiator lower hose	1			\$0.00	
1.31	Radiator spare tank	1			\$0.00	
1.32	Radiator spare tank hose	1			\$0.00	
1.33	Condenser	1			\$0.00	
1.34	Condenser pipe	2			\$0.00	
1.35	Transmission cool	1			\$0.00	
1.36	Transmission cool pipe	1			\$0.00	
1.37	Radiator fan	1			\$0.00	
1.38	Radiator fan cooling	1			\$0.00	
1.39	Engine fan	1			\$0.00	
1.40	Engine fan cowling	1			\$0.00	
1.41	Engine garnish	1			\$0.00	
1.42	Ad-bule tank	1			\$0.00	
1.43	R/H rear view mirror garnish	1			\$0.00	
1.44	R/H rear view mirror assy	1			\$0.00	
1.45	Engine mounting	2			\$0.00	
1.46	Gear box mounting	1			\$0.00	
1.47	Sticker & wording	1			\$0.00	
2	LABOUR					
2.1	Remove & replace wind screen					4
2.2	Replace wind screen moulding					1
2.3	Replace wind screen wiper sensor					1
2.4	Remove & replace dented bonnet					1
2.5	Replace bonnet upper lock					0.5
2.6	Replace bonnet lower lock					0.5
2.7	Replace bonnet insulator					0.5
2.8	Remove & replace bonnet hinge					0.5
2.9	Replace bonnet stand					0.5
2.10	Replace bonnet garnish					0.5
2.11	Putty & spray paint bonnet					2
2.12	Replace bonnet sticker & wording					3
2.13	Spray lacquer over after putting up sticker & wording for bonnet					2

2.14	Remove & replace R/H dented fender					1
2.15	Putty & spray paint R/H fender					1
2.16	Replace R/H fender sticker					1
2.17	Cut & weld R/H fender inner panel					4
2.18	Panel beat & align L/H fender					1
2.19	Remove & replace L/H fender sticker					2
2.20	Putty & spray paint L/H fender					1
2.21	Replace R/H shattered head lamp					1
2.22	Remove & replace R/H head lamp wiper nozzle					1
2.23	Remove & replace front dented bumper					2
2.24	Remove & replace front bumper support					1
2.25	Remove & replace front bumper sensor					1
2.26	Remove & replace R/H fog lamp					1
2.27	Remove & replace front dented number plate					0.5
2.28	Remove & replace siren speaker					1
2.29	Remove & replace siren rumble					1
2.30	Remove & replace AP panel					2
2.31	Putty & spray paint AP panel					2
2.32	Remove & replace radiator grill					0.5
2.33	Remove & replace head lamp support					3
2.34	Remove & replace radiator					4
2.35	Remove & replace radiator upper hose					0.5
2.36	Remove & replace radiator lower hose					0.5
2.37	Remove & replace radiator spare tank					0.5
2.38	Remove & replace radiator spare tank hose					0.5
2.39	Remove & replace dented condenser					2
2.40	Remove & replace condenser pipe					1
2.41	Remove & replace transmission cool					2
2.42	Remove & replace transmission cool pipe					1
2.43	Remove & replace radiator fan					1
2.44	Remove & replace radiator fan cowling					1

Vehicle Inspected By



OI SUN PIN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.