



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CC4/ASM20005276/Eea3q2
8 SHENTON WAY #24-01		Date:	15/11/2021
AXA TOWERSINGAPORE 068811		Code:	ASM
ATTN: CHAN KIAN CHUAN			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YQ 222R	Veh. Inspected	YM 9530M
Policy No.	GA437563	Coverage (\$)	0.00
Claim No.	S0M02MF5	Excess (\$)	0.00
Assign From		Assign Date	17/04/2020
2. Vehicle Particulars & Condition			
Make & Model	ISUZU FVR34	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JALFVR34787000172	Colour	WHITE
Odometer	698442 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	LING LONG	5 mm
L/H Front Tyre	275/70 R22.5	LING LONG	5 mm
R/H Rear Tyre	275/70 R22.5	LING LONG	5 mm
L/H Rear Tyre	275/70 R22.5	LING LONG	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/04/2020	Inspection Date	17/04/2020
Survey held at	TONY AUTOMOTIVE PTE. LTD 8 KAKI BUKIT AVENUE 4 #04-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	