

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

22-Apr-20

Our ref : TP/4837/20

Chye Hup Seng Trading Company

TP AXA

Cecil

MARTER 86H7H581513

RE : estimate cost for vehicle no : GBA 7618T

1 pc	frt rh door <i>Dislod</i>	\$	1,960.00	<i>1130</i>
1 pc	frt rh door protector <i>Rebond</i>		210.00	
2 pcs	frt rh door hinges <i>new</i>		180.00	
1 pc	frt rh door handle <i>new</i>		170.00	
1 pc	frt rh door w/strip <i>lit</i>		236.00	
1 pc	frt rh door lock <i>new</i>		230.00	
1 pc	frt rh door regulator gear <i>NE new</i>		364.00	
1 pc	frt rh door regulator motor <i>new</i>		574.00	
1 pc	frt rh door trimboard <i>NE new</i>		764.00	
1 pc	frt rh door step garnish <i>Dislod</i>		210.00	
1 pc	frt rh door lock switch <i>new</i>		170.00	
1 pc	frt rh pillar rubber <i>new</i>		180.00	
1 pc	rear rh door <i>Dislod</i>		1,760.00	<i>1020</i>
1 pc	rear rh door protector <i>Missing</i>		210.00	
1 pc	rear rh door outer handle <i>new</i>		170.00	
2 pcs	rear rh door hinges <i>Best</i>		180.00	
1 pc	rear rh door lock <i>new</i>		230.00	
1 pc	rear rh door catch <i>new</i>		90.00	
1 pc	rear rh door regulator gear <i>NE new</i>		364.00	
1 pc	rear rh door regulator gear motor <i>new</i>		574.00	
1 pc	rear rh door w/strip <i>lit</i>		230.00	
1 pc	rear rh door trimboard <i>new</i>		764.00	
1 pc	rear rh door pillar rubber <i>new</i>		170.00	
1 pc	centre door pillar <i>Dislod</i>		1070.00	<i>850</i>
1 pc	rocker panel <i>Dislod</i>		860.00	<i>520</i>
1 pc	rear rh door pillar <i>Dislod</i>		1280.00	
1 pc	rear rh fender <i>Ry</i>		1540.00	
1 pc	rear axle <i>new</i>		1980.00	
1 pc	rear rh air duct <i>new</i>		90.00	
			16810.00	
			2521.50	
			14288.50	
1 pc	body sticker <i>new</i>		20.00	<i>snett</i>
1 pc	rear rh tyre <i>Purched</i>		250.00	<i>200</i>
1 pc	rear rh rim <i>Best</i>		250.00	<i>150</i>
			14808.50	

less 15%

400

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : GBA 7618T

Bal brought forward:	\$	14,808.50
Towing.		100.00 ✓
Panel beating.		2000.00 1400 ✓
Spray painting.		2,000.00 1200 ✓
Transfer 2 door parts.	2940	160.00 ✓
Alignment.		80.00 ✓
Undercarriage.		300.00 ✗
		19,448.50
Plus 7% GST		1,361.40
		20,809.90

SD : Twenty thousand eight hundred nine & cents ninety only.

total: 8457
1/5: 35K

Adrian Lj
h/s 23/04/20.
14 Days.

Nett Value : 3.5K.

SL/S.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: