



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC20005397/R1qf3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 12-05-2020		
		Code : LPC2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		GBF 8402R	
Policy No.	Z/20/VC00/106593	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023322	Excess (\$)	500.00	
Assign From	GERALD POH WEE BIN	Assign Date	27/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA26300006D37804	Colour	GREY	
Odometer	102688	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/04/2020	Inspection Date	27/04/2020	
Survey held at	NO. 8 TUAS AVE 18			
Repairer	GOLDBELL ENGINEERING PTE LTD			
5a. Remarks				
A)THE MARKET VALUE IS S\$40,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		