

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1 #03-01, Paya Ubi Industrial Park, Singapore 408934

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To: China Taiping Insurance

Address:

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	-
Date	24/4/2020
Vehicle No	SGP8758C
Make / Model	Suzuki Swift

ZC115172293

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Replaced</i>		\$ 768.00
2 pcs	front bumper side retainer <i>new</i>	\$ 55.00	\$ 110.00
1 pc	front bumper reinforcement (top) <i>Best</i>		\$ 248.00
1 pc	front bumper reinforcement (low) <i>Best</i>		\$ 272.00
2 pc	front fog lamp <i>Cracked RH</i>	\$ 195.00	\$ 390.00
2 pc	front fog lamp garnish <i>at RH</i>	\$ 85.00	\$ 170.00
2 pc	front bumper clip <i>new</i>		\$ 30.00
1 set	front grille <i>cracked</i>		\$ 193.00
1 pc	front bumper lower grille <i>Replaced</i>	\$ 72.50	\$ 145.00
2 pc	front grille "S" emblem <i>new</i>		\$ 48.00
2 pc	headlamp <i>RT Cracked, LH Cracked</i>	\$ 475.00	\$ 950.00
1 pc	bonnet <i>Buckled</i>		\$ 587.00
1 pc	o/s front fender <i>2x Cracked</i>		\$ 285.00
1 pc	o/s front fender inner garnish <i>new</i>		\$ 87.00
1 set	o/s front fender inner garnish clip <i>new</i>		\$ 30.00
2 pcs	front bumper lower spoiler <i>Replaced RH</i>	\$ 455.00	\$ 910.00
1 pc	aircon condenser <i>74m</i>		\$ 570.00
1 pc	condenser bracket <i>74m</i>		\$ 47.00
1 pc	lower air resonator <i>74m</i>		\$ 85.00
1 pc	front support panel <i>Buckled</i>		\$ 655.00
1 pc	front lock top garnish <i>new</i>		\$ 72.00
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,000.00
2	to putty and spray painting on affected area		\$ 800.00
3	anti rust		\$ 150.00
4	R&R wiring		\$ 80.00
5	R&R aircon		\$ 120.00
	Subtotal:		\$ 8,802.00

Adrian

2/5 27/04/20

06 Days

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

\$4K