



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD20002792/Eqf3e2-1

6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER
4 SINGAPORE 038986

Date : 08-05-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 6924L	Veh. Inspected	SLB 7652U
Policy No.	PNPV2019-00008319	Coverage (\$)	0.00
Claim No.	1202000007933	Excess (\$)	0.00
Assign From	CLARA LI ZI RONG	Assign Date	27/04/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM44A8G0339828	Colour	RED
Odometer	59638	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50Z R17	MICHELIN	6 mm
L/H Front Tyre	215/50Z R17	MICHELIN	6 mm
R/H Rear Tyre	215/50Z R17	MICHELIN	6 mm
L/H Rear Tyre	215/50Z R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/02/2020	Inspection Date	19/02/2020
Survey held at	EVERDAWN AUTO SERVICE 8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------