

KZ

(m)

28/1/19

# AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

*Not Authorised*  
*11 Sep @ 3800*  
*Resurvey After Paint*  
*4 days*

VINCENT KOH YAM HWEE  
c/o 46 Lentor Plain  
Singapore 786548

Date: 06-01-17

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE: CITREON PICASSO / SJU102K</b>		
1 pc	front bumper	Sm 1,070.00 X
1 pc	front bumper fog lamp cover	Sm 460.00 X
1 pc	front fender	R 656.00 X
1 pc	front fender sticker"picasso"	Sm 89.00
1 pc	front door	Red/wrap 1,070.00
1 pc	front door protector	Sm 340.00
1 pc	front bumper fog lamp cover chrome moulding	Sm 175.00 X
1 pc	front door side mirror assy	CPM 1,077.00
1 pc	front alloy rim	Red 680.00
1 pc	front alloy rim cover	Adl Covt Sm 180.00 X
1 pc	front lower arm	Sm 315.00 X
1 pc	front shock absorber	BA Sm 478.00 X
1 pc	front knuckle arm	BA Sm 560.00 X
1 pc	front wheel bearing	Sm 170.00 X
1 pc	front wheel hub	Sm 240.00 X
1 pc	front steering tie rod	Sm 215.00 X
1 pc	front steering rod end ball joint	Sm 160.00 X
	$\$4,644.00$ $\times 90\%$ $\$4,179.60$ $+ 1295.00$ $\$5,474.60$ $\times 80\%$ $\$4,379.68$ $= \text{L\$ } 4,380.00$	sub-total 7,935.00 3986
	To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.	860.00 4501
	To check wiring system and repair wiring system.	50.00 151
	To apply rust proofing on affected areas.	100.00 301
	To apply putty and spray painting on affected areas.	1,200.00 6801
	To perform 4 wheels computerised alignment.	85.00 601
	To remove and install front undercarriage parts to enable repair.	300.00 601
	<b>Total:</b>	<b>10,530.00</b> 1295

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Work Order: R016576  
 VIN: SJU102K  
 Year: 09  
 Date: 4.1.17 15:49



Citroën : C4 Picasso : 2006-13 : except Rough Road Suspension : Steel Suspension

Front : Left

Actual	Before	Specified Range
0°16'	0°16'	-0°20' 0°40'
3°48'	3°48'	4°24' 5°24'
-0°03'	-0°04'	-0°15' -0°06'
13°21'	13°21'	11°02' 12°02'
13°38'	13°38'	10°42' 12°42'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°26'	-2°25'	-0°40' 0°20'
3°57'	3°57'	4°24' 5°24'
-0°21'	-0°22'	-0°15' -0°06'
13°33'	13°33'	11°22' 12°22'
11°07'	11°07'	10°42' 12°42'

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
2°42'	2°42'	-0°20' 0°20'
-0°09'	-0°09'	-0°20' 0°20'
-0°12'	-0°11'	-0°20' 0°20'
-0°24'	-0°25'	-0°30' -0°12'

Rear : Left

Actual	Before	Specified Range
-1°31'	-1°32'	-2°12' -1°12'
0°20'	0°21'	0°20' 0°32'

Camber  
 Toe

Rear : Right

Actual	Before	Specified Range
-1°22'	-1°21'	-2°12' -1°12'
0°16'	0°15'	0°20' 0°32'

Rear

Cross Camber  
 Total Toe  
 Thrust Angle  
 Axle Offset

Actual	Before	Specified Range
-0°09'	-0°10'	-0°20' 0°20'
0°36'	0°36'	0°43' 1°01'
0°02'	0°03'	-0°06' 0°06'
0mm	0mm	