



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20005444/Eqf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 14-05-2020



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFM 2286P	Veh. Inspected	SMG 5892T
Policy No.		Coverage (\$)	0.00
Claim No.	SFM 2286P	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	28/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU60J036381	Colour	BLACK
Odometer	115977	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/04/2020	Inspection Date	28/04/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**