

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55082
Date Estimated : 28/04/2020
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Choong Zhi Jie (Zhong ZhiJie)
12A Hougang Street 11
#10-58

Singapore 534074

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT1123M	WBAJR12090BR79774	30/01/2020	520i	0

DESCRIPTION	VALUE
Replacing front bumper panel and attachment	850 1,275.00
Spray front bumper	934 1,038.00
To replace left headlight	450 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries	80 / ? 150.00

Total Labour 1: 3,121.00

DESCRIPTION	QTY	PRIC	VALUE
COVER GRILLE LH Xnn	1	76.25	76.25
LH GRILLE AIR INLET OPEN (LINES) Xnn	1	116.45	116.45
FRT BUMPER CARRIER ? Xnn	1	726.70	726.70
LH GUIDE TOP ? Xnn	1	36.20	36.20
RH BUMPER GUIDE ? Xnn	1	16.95	16.95
FRT BUMPER BOTTOM CARRIER (M) ? Xnn	1	399.70	399.70
FRT BUMPER PANEL PRIMED (PMA/PDC) cut	1	1,377.95	1,377.95
FRT BUMPER BOTTOM IMPACT ABSORBER (? Xnn	1	63.00	63.00
Impact absorber)	1	63.00	63.00
FRT LH GRILLE (M/SPORT) ? Xnn	1	145.70	145.70
LH HEADLIGHT MOUNTING ? Xnn	1	140.90	140.90
LH HEADLIGHT LED AHL HIGH (ICON'LIG bn	1	4,879.55	4,879.55

Total Parts : 8,042.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55082
Date Estimated : 28/04/2020
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT1123M	WBAJR12090BR79774	30/01/2020	520i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 09/06/2020 @ 1135 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 900 10668 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	3,121.00
Parts	:	8,042.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	781.43
Grand Total	:	11,944.78

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **