

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

LKL: Ashur

Not Authorised
Hale
30/4/20
L/S 1400/
3 days.

M/S : INDIA INTERNATIONAL INSURANCE

Estimate No: M00153

Date: 30-Apr-20

Veh Reg No : SLR9449T

Make/Model: MAZDA3

Chassis No: JM6BN22A8H0162668

Engine No: P520454862

Reg. Date : 24/07/2017

ATTN: Motor Claim Department

Your Ref No: SLR9449T

Claim Type: THIRD PARTY CLAIM

Accident Date: : 28.04.20

Estimate Repair Cost to Vehicle No : SLR9449T

PAGE:1/1

S/N	Description	Quantity	Unit	Price S\$	Amount S\$
NETT PRICE					
1	Front Door - LH	1	PCS	1046.20	1046.20 X
2	Front Door Rubber - LH	1	PCS	246.40	246.40 X
3	Rear Door - LH	1	PCS	1024.40	1024.40 ✓
4	Rear Door Hinge Lower - LH	1	PCS	50.20	50.20 X
5	Rear Door Rubber - LH	1	PCS	226.40	226.40 X
TOTAL				2593.60	2593.60
Less 20%				2074.88	2074.88

LABOUR CHARGES

6	Panel Beating	300	750.00
7	To Remove & Refit Door Assy	50	160.00
8	To Check Wiring	11 X	80.00
9	To Spray Paint	600	750.00

TOTAL	1740.00
--------------	----------------

OVERALL TOTAL	3814.88
----------------------	----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD

P-1024.4
202
P-819.52
L-950.00
1769.52
202
1418

AUTHORISE SIGNATURE